

FORM

6

Rev
12/05

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109



DE ET OE ES

Date Received:

Document Number:

400150035

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 16700 Contact Name: ROY CRAMER
 Name of Operator: CHEVRON PRODUCTION COMPANY Phone: (970) 675-3719
 Address: 100 CHEVRON RD Fax: (970) 675-3800
 City: RANGELY State: CO Zip: 81648 Email: RWCR@CHEVRON.COM

24 hour notice required, contact: Name: LONGWORTH, MIKE Tel: (970) 812-7644
 Email: mike.longworth@state.co.us

API Number 05-103-08736-00
 Well Name: WALBRIDGE, L B Well Number: 4X
 Location: QtrQtr: NWNE Section: 1 Township: 1N Range: 102W Meridian: 6
 County: RIO BLANCO Federal, Indian or State Lease Number: 47443
 Field Name: RANGELY Field Number: 72370

Notice of Intent to Abandon Subsequent Report of Abandonment

Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.091580 Longitude: -108.789650
 GPS Data:
 Data of Measurement: 01/23/2008 PDOP Reading: 3.6 GPS Instrument Operator's Name: John Floyd
 Reason for Abandonment: Dry Production for Sub-economic Mechanical Problems
 Other UN ECONOMICAL TO REPAIR FLOWLINE LEAK
 Casing to be pulled: Yes No Top of Casing Cement: _____
 Fish in Hole: Yes No If yes, explain details below
 Wellbore has Uncemented Casing leaks: Yes No If yes, explain details below
 Details: _____

Current and Previously Abandoned Zones

Formation	Code	Perf. Top	Perf. Bottom	Date	Method of Isolation	Plug Depth
WEBER	WEBR	5915	6338			

Total: 1 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
CONDUCTOR	20+0/8	16+0/8	78	30	1	30	0	VISU
SURF	12+1/4	9+5/8	36	3,027	775	3,027	0	VISU
2ND	8+3/4	7+0/8	23	6,456	870	6,456	1,180	CBL

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 5865 with 9 sacks cmt on top. CIBP #2: Depth _____ with _____ sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 37 sks cmt from 5865 ft. to 5990 ft. in Plug Type: CASING Plug Tagged:

Set 48 sks cmt from 2777 ft. to 3277 ft. in Plug Type: CASING Plug Tagged:

Set 48 sks cmt from 0 ft. to 250 ft. in Plug Type: CASING Plug Tagged:

Set _____ sks cmt from _____ ft. to _____ ft. in Plug Type: _____ Plug Tagged:

Set _____ sks cmt from _____ ft. to _____ ft. in Plug Type: _____ Plug Tagged:

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

(Cast Iron Cement Retainer Depth)

Set _____ sacks half in. half out surface casing from _____ ft. to _____ ft. Plug Tagged:

Set _____ sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing Plugging Date: _____

*Wireline Contractor: _____ *Cementing Contractor: _____

Type of Cement and Additives Used: _____

Flowline/Pipeline has been abandoned per Rule 1103 Yes No *ATTACH JOB SUMMARY

Provide Technical Detail:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: DIANE L PETERSON

Title: REGULATORY SPECIALIST Date: _____ Email: DLPE@CHEVRON.COM

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: _____ Date: _____

CONDITIONS OF APPROVAL, IF ANY: _____ Expiration Date: _____

Attachment Check List

Att Doc Num	Name
400150042	OTHER
400150044	PROPOSED PLUGGING PROCEDURE
400150045	WELLBORE DIAGRAM
400150050	

Total Attach: 4 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>

Total: 0 comment(s)