



OUR INVOICE

198920

32-588

REC'D EUSD

FEB 04 2011

(P.O. # 103794)

Date <u>1/31/11</u>	Well Owner <u>PDC</u>	Well No. <u>10TD</u>	Lease <u>PURVIS</u>
County <u>Weld</u>	State <u>Colorado</u>		Field
Charge to <u>ENSIGN US Drilling</u>			Charge Code
Address <u>P.O. Box 17805 (ENSIGN # 39)</u>			For Office Use Only
City, State <u>Denver, Colorado 80217</u>			
Pump Truck No. <u>1200</u>	Code	Bulk Truck No. <u>1217</u>	Code
Type of Job		Depth	Fr. <u>675</u>
Surface <u>8 5/8" (56-24")</u>		Bottom of Surface	Fr. <u>664</u>
Plug		Plug Landed @ <u>659</u>	Time On <u>655K</u>
Production		Pipe Landed @ <u>664</u>	Time Off <u>Plug Down 0900</u>

Reference No.	Description	Qty.	Meas.	Unit Price	Amount
	Pump Truck Charge				
	Cement Nests ✓	470	SKS		
	Poz. Mix				
	Calcium Chloride	3%			
	Gel % Flo-Calc $\frac{1}{4}$ #Per Sack				
	Handling Charge				
	Hauling Charge				
	Additional Cement				
	Mixing Rate - 4 BPM / Displacement Rate - 4 BPM				
	Slurry Vol - 1.18 CU FT / SK-Slurry / WT 15.2 PPG				
	Total Slurry Vol 98.5 BBLs Cement				
	Landed Plug @ 27.5 PSI / Water Temp 130°F				

Remarks: Pre-Flush w/ 20 BBLs H ² O		Tax Reference Code		Sub Total	
Displace w/ 41 BBLs H ² O		State Co 2.9 %		Tax	
Circulate 5 BBLs Cement		Disc.		Total	

Truck No.	Code	State Mileage	Nebraska	Colorado	Wyoming
1000		Pump Truck		31	
1217		Bulk Truck		31	

We do not assume any responsibility for any damage or conditions resulting from our services. All pricing is subject to

Delivered By Justin Dallas & James

Received By

Customer or His Agent