

BUREAU OF LAND MANAGEMENT
W/O MAJOR UNDESIRABLE EVENT (MUE) REPORTING FORMAT

BLM Office Reporting: White River Field Office – Meeker, CO																		
BLM Employee: Christina Barlow																		
Company Official Reporting to BLM: Reed Haddock																		
Operator: BOPCO, L.P.																		
Date/Time of Occurrence: 08-23-2010 – 5:30AM			Date/Time BLM Notified: 08-23-2010 – 11AM															
Field/Unit Name: Yellow Creek Field			Lease Number: COC 59393															
State: CO	County: Rio Blanco	Twp: 1S	Rng: 98W	Sec: 3	Qtr: NESE													
Surface Ownership: (circle one)		Federal	Indian	State	FEE													
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td rowspan="3" style="width: 30%;">Type of Event: (circle one)</td> <td style="width: 15%;">Oil Spill</td> <td style="width: 15%;">Oil/Water Spill</td> <td style="width: 15%;">Gas Venting</td> <td style="width: 15%;">Toxic Fluid Spill</td> </tr> <tr> <td>Saltwater Spill</td> <td>Other Spill (Specify)</td> <td>Blowout</td> <td>Fire</td> </tr> <tr> <td>Injury</td> <td>Fatality</td> <td>Property Damage</td> <td>Explosion</td> </tr> </table>						Type of Event: (circle one)	Oil Spill	Oil/Water Spill	Gas Venting	Toxic Fluid Spill	Saltwater Spill	Other Spill (Specify)	Blowout	Fire	Injury	Fatality	Property Damage	Explosion
Type of Event: (circle one)	Oil Spill	Oil/Water Spill	Gas Venting	Toxic Fluid Spill														
	Saltwater Spill	Other Spill (Specify)	Blowout	Fire														
	Injury	Fatality	Property Damage	Explosion														
<p>Nature and Cause of Event: A leak was discovered in the buried water pipeline 50' past the cattle guard as one turns off CR 20 and drives up the access road to the pad. All water stayed in the ditch then crossed under the cattle guard and diverted into a dry creek bed on DOW surface. The water line has been isolated and all flow stopped. BOPCO, L.P. will have to dig the buried pipe-line up to find out why this happened and then repair. It is estimated that 70 bbls. of produced water leaked into the ditch. A small portion of this spill was on BLM surface. The rest of the spill occurred on DOW surface. All water was absorbed into the ditch. BOPCO, L.P. has called Olsson Associates to conduct sampling.</p>																		
Environmental Impact: None.																		
Time Required to Control Event (Hours):			< 1 hour															
Volumes Discharged or Consumed:			Estimated 70 bbls.															
Volumes Recovered:			Sampling in progress.															
Action Taken to Control Event: The water pipeline needs to be dug up and repaired. This will occur after proper sampling has been conducted.																		
Resultant Damage: None.																		
Clean-Up Procedures: BOPCO will have the soil tested and verify that it meets COGCC standards according to Series 900 rules. Once the soil results are in the necessary clean-up will be conducted and reported to BLM, DOW, and COGCC.																		
Cause/Extent of Personal Injury: None.																		
Agency Notification List: (Federal/State/Local):		Agency Name		Contact Name														
		COGCC		Chris Canfield														
		BOPCO, L.P.		Tony Savoie, EH&S														
		BLM – Meeker, CO		Christina Barlow														
		DOW – Meeker, CO		Ed Winters														
Remarks: This event was contained by isolating the water pipeline. BOPCO, L.P. will have the soil in the ditch tested and the results will be submitted in a report to the BLM, COGCC, and																		

DOW.