

From: LLindow@nobleenergyinc.com
To: [Koepsell, Arthur](#)
Subject: Re: Pletcher 31-35 Form 2A #400215437, Noble
Date: Thursday, October 20, 2011 3:20:23 PM

Noble concurs with this COA.

Liz Lindow
Regulatory Analyst
Noble Energy, Inc.
1625 Broadway, Suite 2200
Office: 720-587-2079
Cell: 303-590-8789

From: "Koepsell, Arthur" <Arthur.Koepsell@state.co.us>
To: <llindow@nobleenergyinc.com>
Date: 10/20/2011 03:13 PM
Subject: Pletcher 31-35 Form 2A #400215437, Noble

Liz,

The COGCC is reviewing the Form 2A (#400215437) for the Noble Pletcher 31-35 location, located in the NWNE Sec 35 T1N R47W Yuma County, Colorado. The COGCC requests the following changes regarding the data submitted on or attached to the Form 2A prior to passing the Oil and Gas Location Assessment (OGLA).

Due to the Valent sand, 9 to 15 percent slopes soil type the following COA will apply:

· Best management practices (BMPs) should be utilized to minimize disturbance of the vegetative cover while constructing and operating the location and to aid soil stabilization and revegetation of the disturbed area during interim reclamation. Cut and fill slopes should be minimized to the greatest extent practicable. The BMPs may include, but shall not be limited to, the use of mulches and/or tackifiers, erosion control mats and/or blankets, appropriate seed mixes and/or soil amendments and any other practices necessary to prevent soil erosion by wind and stormwater, and to encourage the growth of desirable soil stabilizing vegetation.

Please feel free to contact me if you have any questions or concerns.

Thanks,

Arthur

Arthur W. Koepsell, P.G.
Oil & Gas Location Assessment Specialist
Southern Area

Oil and Gas Location Assessment
Colorado Oil and Gas Conservation Commission
1120 Lincoln St. Suite 801

Denver Colorado 80203
Phone (303) 894-2100 ext. 5148

The information contained in this e-mail and any attachments may be confidential. If you are not the intended recipient, please understand that dissemination, copying, or using such information is prohibited. If you have received this e-mail in error, please immediately advise the sender by reply e-mail and delete this e-mail and its attachments from your system.