

Allison, Rick

From: Kallasandra Moran [k Moran@petro-fs.com]
Sent: Thursday, November 24, 2011 1:26 PM
To: Allison, Rick
Subject: RE: Hergert Well Locations and Facility Form 2As 400220660, 400220935, 400221034, 400221045

Rick,

Please see responses in red below...

Thanks!

Kallasandra M. Moran

Regulatory Manager

[Petroleum Field Services](#)

Office: 303-928-7128 ext 236

Cell: 720-903-6686

Fax: 303-962-6237

1801 W. 13th Ave.

Denver, CO 80204



Use our resources to find yours!

Providing service that exceeds expectations.

Confidentiality Notice: This e-mail message and attachments are only for the use of the intended recipient and may contain information that is privileged, confidential or exempt from disclosure under applicable law. If you are not the intended recipient, any disclosure, distribution or other use of this e-mail message or attachments is prohibited. If you have received this e-mail in error, please delete and notify the sender immediately. In addition, please be aware that any messages addressed to our domain are subject to archiving and review by persons other than the intended recipient.



Please recycle and consider the environment before printing this email.

From: Allison, Rick [<mailto:Rick.Allison@state.co.us>]
Sent: Monday, November 07, 2011 3:06 PM
To: Kallasandra Moran
Subject: Hergert Well Locations and Facility Form 2As 400220660, 400220935, 400221034, 400221045

Kallasandra,

I am reviewing the Form 2A location assessments (Doc #s 400220660, 400220935, 400221034, 400221045) for the Hergert 1-35, 8-35 and 17-35 well locations and the Hergert 1-35 Facility location in the NE ¼ Sec35 T7N R66W, Weld County and have the following comments.

1. I have changed the Sensitive Area Designation to Yes because shallow ground water is present. Since closed loop drilling will be used and no pits are requested on the location, no additional conditions are attached relative to shallow ground water protection. **This is fine**
2. Please submit a revised Waste Management Plan per our previous discussions. **Submitted previously**

3. Ground water is reportedly 6 feet in the area of the proposed wells and facility. How will Bayswater construct the tank battery at the Hergert 1-35 Facility location to prevent spilled or released fluids from impacting the shallow unconfined aquifer? [See email dated 11/24/2011 regarding BMP.](#)

Please contact me with any questions regarding these Form 2As.

Best Regards,

Rick Allison, P.G.
Oil and Gas Location Assessment Specialist
Colorado Oil and Gas Conservation Commission
1120 Lincoln Street, Suite 801
Denver, CO 80203
303-894-2100 ext 5102