

**From:** [Bob Noonan](#)  
**To:** [Yokley, Bill](#)  
**Subject:** FW: Questions on the Single Eagle #1 API# 113-06159  
**Date:** Thursday, January 26, 2012 11:20:26 AM

---

Bill,

Let me know if you need more information than what has been provided below. Thanks.

Bob Noonan  
Patara Oil & Gas LLC  
513.503.3820 (mobile)  
303.563.5377 (office)

---

**From:** Mike Lo  
**Sent:** Thursday, January 26, 2012 11:18 AM  
**To:** Bob Noonan; Robert Swartwout  
**Subject:** RE: Questions on the Single Eagle #1 API# 113-06159

Hope this helps:

Honaker Trail	7695
La Sal	8713
Hatch	9211
Ismay	9653
Hovenweep	9736

Mike Lo  
Sr. Geoscience Technician  
Patara Oil & Gas, LLC  
600 17th Street, Suite 1900S  
Denver, CO 80202  
Office: 303-563-5363  
Fax: 720-235-4560  
Cell: 303-601-1215

---

**From:** Bob Noonan  
**Sent:** Thursday, January 26, 2012 11:04 AM  
**To:** Mike Lo; Robert Swartwout  
**Subject:** FW: Questions on the Single Eagle #1 API# 113-06159

Can either of you help with this request? I can't find any top info in the electronic wellfile.

Bob Noonan  
Patara Oil & Gas LLC  
513.503.3820 (mobile)  
303.563.5377 (office)

---

**From:** Yokley, Bill [<mailto:Bill.Yokley@state.co.us>]  
**Sent:** Thursday, January 26, 2012 7:59 AM  
**To:** Bob Noonan

**Subject:** Questions on the Single Eagle #1 API# 113-06159

Good morning,

Trying to work the sundry for recompletion on the Single Eagle #1.

Issue: On review of the well file it shows that only one formation top was furnished.

Would you furnish all formation tops from the Honaker Trail to TD?

Thanks,

Bill