

FORM
5A

Rev
02/08

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Document Number:

400275416

Date Received:

COMPLETED INTERVAL REPORT

The completed interval Report, Form 5A, shall be submitted within thirty (30) days of completing a formation (successful or not), when a formation is temporarily abandoned or permanently abandoned, for a recompletion, reperforation or restimulation, or when a formation is commingled. Fill out a section for each formation. Attach as many pages as required to fully describe the work. List in order of completion.

1. OGCC Operator Number: 66561

4. Contact Name: Joan Proulx

2. Name of Operator: OXY USA INC

Phone: (970) 263-3641

3. Address: PO BOX 27757

Fax: (970) 263-3694

City: HOUSTON State: TX Zip: 77227

5. API Number 05-077-09379-00

6. County: MESA

7. Well Name: MCDANIEL

Well Number: 2-7C

8. Location: QtrQtr: NENE Section: 2 Township: 9S Range: 94W Meridian: 6

9. Field Name: BRUSH CREEK Field Code: 7562

Completed Interval

FORMATION: WILLIAMS FORK - CAMEO

Status: PRODUCING

Treatment Date: 07/02/2008

Date of First Production this formation: 07/04/2008

Perforations Top: Bottom: 8098 No. Holes: 129 Hole size: 34/100

Provide a brief summary of the formation treatment:

Open Hole: ☐

6 stages of slickwater frac with 13,277 bbls of frac fluid and 500,721 lbs of white sand proppant

This formation is commingled with another formation: ☐ Yes ☒ No

Test Information:

Date: 04/05/2012 Hours: 0 Bbls oil: 0 Mcf Gas: 10 Bbls H2O: 2

Calculated 24 hour rate: Bbls oil: 0 Mcf Gas: 20 Bbls H2O: 5 GOR: 0

Test Method: Flowing Casing PSI: 562 Tubing PSI: 397 Choke Size: 22/64

Gas Disposition: SOLD Gas Type: DRY BTU Gas: 1039 API Gravity Oil: 0

Tubing Size: 2 + 3/8 Tubing Setting Depth: 7700 Tbg setting date: 03/29/2012 Packer Depth:

Reason for Non-Production:

Date formation Abandoned: Squeeze: ☐ Yes ☐ No If yes, number of sacks cmt

Bridge Plug Depth: Sacks cement on top:

Comment:

Repair work occurred on McDaniel 2-7C as holes in the tubing were suspected. No holes in the tubing were found, tubing was re-landed and the well was returned to production.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed:

Print Name: Joan Proulx

Title: Regulatory Analyst

Date:

Email joan_proulx@oxy.com

Attachment Check List

Att Doc Num	Name

Total Attach: 0 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>

Total: 0 comment(s)