

FORM
6Rev
12/05

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE ET OE ES

Document Number:

400277116

Date Received:

02/01/2012

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number:	5	Contact Name:	Ryan Hollinshead
Name of Operator:	COLORADO OIL & GAS CONSERVATION	Phone:	(303) 894-2100 x5134
Address:	1120 LINCOLN ST SUITE 801	Fax:	(303) 894-2109
City:	DENVER	State:	CO
Zip:	80203	Email:	Ryan.Hollinshead@state.co.us
For "Intent" 24 hour notice required,		Name:	LEONARD, MIKE
		Tel:	(719) 647-9715
COGCC contact:		Email:	mike.leonard@state.co.us

API Number	05-043-40092-00		
Well Name:	HW-3419S69W	Well Number:	3
Location:	QtrQtr: NESW	Section:	34
	Township:	19S	Range: 69W
	Meridian:	6	
County:	FREMONT	Federal, Indian or State Lease Number:	
Field Name:	FLORENCE-CANON CITY	Field Number:	24600

☒ Notice of Intent to Abandon ☐ Subsequent Report of Abandonment

Only Complete the Following Background Information for Intent to Abandon

Latitude:	38.350770	Longitude:	-105.101395
GPS Data:			
Date of Measurement:	03/15/2011	PDOP Reading:	2.5
GPS Instrument Operator's Name:	Mike Leonard		
Reason for Abandonment:	<input type="checkbox"/> Dry <input type="checkbox"/> Production for Sub-economic <input type="checkbox"/> Mechanical Problems		
<input checked="" type="checkbox"/> Other Orphan Well			
Casing to be pulled:	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Top of Casing Cement:	455
Fish in Hole:	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If yes, explain details below	
Wellbore has Uncemented Casing leaks:	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If yes, explain details below	
Details:			

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
PIERRE	1500	3000			

Total: 1 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
SURF	10+5/8	8+5/8	24	100	20	100	0	CALC
1ST	7+7/8	6	18	3,000	185	3,000	1,500	CALC

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth _____ with _____ sacks cmt on top. CIPB #2: Depth _____ with _____ sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIPB #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 210 sks cmt from 455 ft. to 0 ft. Plug Type: STUB PLUG Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

(Cast Iron Cement Retainer Depth)

Set _____ sacks half in. half out surface casing from _____ ft. to _____ ft. Plug Tagged: ☐

Set _____ sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☐ No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing Plugging Date: _____

*Wireline Contractor: _____ *Cementing Contractor: _____

Type of Cement and Additives Used: _____

Flowline/Pipeline has been abandoned per Rule 1103 ☐ Yes ☐ No *ATTACH JOB SUMMARY

Technical Detail/Comments:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Ryan Hollinshead

Title: Northeast Area Engineer Date: 2/1/2012 Email: Ryan.Hollinshead@state.co.us

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: HOLLINSHEAD, RYAN Date: 4/26/2012

CONDITIONS OF APPROVAL, IF ANY: _____ Expiration Date: 10/25/2012

Attachment Check List

Att Doc Num	Name

Total Attach: 0 Files

General Comments

User Group	Comment	Comment Date

Total: 0 comment(s)