

FORM
6Rev
12/05

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Document Number:

2170337

Date Received:

08/03/2012

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 54380

Contact Name: DAVID BLANDFORD

Name of Operator: MATRIX ENERGY LLC

Phone: (970) 247-1959

Address: 1241 THOROUGHbred ROAD

Fax: (970) 247-2359

City: DURANGO State: CO Zip: 81303

Email: ANDELEENERGY@GMAIL.COM

For "Intent" 24 hour notice required,

Name: EDELEN, RANDY

Tel: (970) 520-2531

COGCC contact:

Email: randy.edelen@state.co.us

API Number 05-001-07890-00

Well Name: ANDERSON

Well Number: 2

Location: QtrQtr: NWNE Section: 10 Township: 2S Range: 61W Meridian: 6

County: ADAMS

Federal, Indian or State Lease Number:

Field Name: SUN

Field Number: 80200

☒ Notice of Intent to Abandon☐ Subsequent Report of Abandonment

Only Complete the Following Background Information for Intent to Abandon

Latitude: 39.896944

Longitude: -104.195556

GPS Data:

Date of Measurement: 12/11/2009

PDOP Reading: 2.2

GPS Instrument Operator's Name: CODY HOBBS

Reason for Abandonment: ☐ Dry☒ Production for Sub-economic☐ Mechanical Problems☐ OtherCasing to be pulled: ☒ Yes☐ No

Estimated Depth:

Fish in Hole: ☐ Yes☒ No

If yes, explain details below

Wellbore has Uncemented Casing leaks: ☐ Yes☒ No

If yes, explain details below

Details:

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
D SAND	6702	6714			

Total: 1 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
SURF	12+1/4	8+5/8	24	207	200	207	0	
1ST	7+7/8	4+1/2	11.6	6,773	200	6,773	5,973	CALC

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 6650 with 2 sacks cmt on top. CIBP #2: Depth _____ with _____ sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 50 sks cmt from 5000 ft. to 4000 ft. Plug Type: STUB PLUG Plug Tagged: ☒

Set 165 sks cmt from 670 ft. to 260 ft. Plug Type: OPEN HOLE Plug Tagged: ☒

Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐

Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐

Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

(Cast Iron Cement Retainer Depth)

Set 110 sacks half in. half out surface casing from 260 ft. to 0 ft. Plug Tagged: ☐

Set 0 sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☒ No

Set 0 sacks in rat hole Set 0 sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing Plugging Date: _____

*Wireline Contractor: _____ *Cementing Contractor: _____

Type of Cement and Additives Used: _____

Flowline/Pipeline has been abandoned per Rule 1103 ☐ Yes ☐ No *ATTACH JOB SUMMARY

Technical Detail/Comments:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: DAVID BLANDFORD

Title: _____ Date: 7/31/2012 Email: ANDELEENERGY@GMAIL.COM

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: BURN, DIANA Date: 8/10/2012

CONDITIONS OF APPROVAL, IF ANY:

Expiration Date: 2/9/2013

File Form 15 Pit Report for pit(s) present even if at common battery, if pit to be closed file Form 27 for prior approval of remediation.

1) Provide 24 hour notice of MIRU to Randy Edelen at 970-520-2531 or e-mail at Randy.Edelen@state.co.us. 2) For 670' plug: pump plug and displace, shut-in, WOC 4 hours and tag plug, must be 280' or shallower. Leave at least 100' cement in the casing for each plug. If 260' plug not circulated to surface top off surface with 10 sx. 3) Properly abandon flowlines as per Rule 1103.

Attachment Check List

Att Doc Num	Name
2170337	WELL ABANDONMENT REPORT (INTENT)
2170338	WELLBORE DIAGRAM
400314690	FORM 6 INTENT SUBMITTED

Total Attach: 3 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>

Total: 0 comment(s)