

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 601, Denver, Colorado 80203 Phone: (303)894-2100 Fax: (303)894-2109

## SUNDRY NOTICE

Submit original plus one copy. This form is to be used for general, technical and environmental sundry information. For proposed or completed operations, describe in full on Technical Information Page (Page 2 of this form.) Identify well or other facility by API Number or by OGCC Facility ID. Operator shall send an informational copy of all sundry notices for wells located in High Density Areas to the Local Government Designee (Rule 603b.)

1. OGCC Operator Number: 96850	4. Contact Name: Greg Davis	Complete the Attachment Checklist
2. Name of Operator: WPX Energy Rocky Mountain, LLC	Phone: 303-606-4071	
3. Address: 1001 17th Street, Suite 1200	Fax: 303-629-8268	OP OGCC
City: Denver State: CO Zip: 80202		
5. API Number 05-045-10236-00	OGCC Facility ID Number	Survey Plat
6. Well/Facility Name: Williams	7. Well/Facility Number GM 414-27	Directional Survey
8. Location (Qtr/Qtr, Sec, Twp, Rng, Meridian): SWSW Section 27-T6S-R96W 6th PM		Surface Equip Diagram
9. County: Garfield	10. Field Name: Grand Valley	Technical Info Page X
11. Federal, Indian or State Lease Number:		Other

RECEIVED  
NOV 06 2012  
COGCC/Rifle Office

## General Notice

<input type="checkbox"/> CHANGE OF LOCATION: Attach New Survey Plat (a change of surface qtr/qtr is substantive and requires a new permit)	
Change of Surface Footage from Exterior Section Lines:	<input type="checkbox"/> FNL/FSL <input type="checkbox"/> FEL/FWL
Change of Surface Footage to Exterior Section Lines:	<input type="checkbox"/>
Change of Bottomhole Footage from Exterior Section Lines:	<input type="checkbox"/>
Change of Bottomhole Footage to Exterior Section Lines:	<input type="checkbox"/> attach directional survey
Bottomhole location Qtr/Qtr, Sec, Twp, Rng, Mer	
Latitude	Distance to nearest property line
Longitude	Distance to nearest bldg, public rd, utility or RR
Ground Elevation	Distance to nearest lease line
	Is location in a High Density Area (rule 603b)? Yes/No
	Distance to nearest well same formation
	Surface owner consultation date:
GPS DATA:	
Date of Measurement	PDOP Reading
	Instrument Operator's Name
<input type="checkbox"/> CHANGE SPACING UNIT	<input type="checkbox"/> Remove from surface bond
Formation Formation Code Spacing order number Unit Acreage Unit configuration	Signed surface use agreement attached
<input type="checkbox"/> CHANGE OF OPERATOR (prior to drilling):	<input type="checkbox"/> CHANGE WELL NAME
Effective Date:	From:
Plugging Bond: <input type="checkbox"/> Blanket <input type="checkbox"/> Individual	To:
	Effective Date:
<input type="checkbox"/> ABANDONED LOCATION:	<input type="checkbox"/> NOTICE OF CONTINUED SHUT IN STATUS
Was location ever built? <input type="checkbox"/> Yes <input type="checkbox"/> No	Date well shut in or temporarily abandoned:
Is site ready for inspection? <input type="checkbox"/> Yes <input type="checkbox"/> No	Has Production Equipment been removed from site? <input type="checkbox"/> Yes <input type="checkbox"/> No
Date Ready for Inspection:	MIT required if shut in longer than two years. Date of last MIT
<input type="checkbox"/> SPUD DATE:	<input type="checkbox"/> REQUEST FOR CONFIDENTIAL STATUS (6 mos from date casing set)
<input type="checkbox"/> SUBSEQUENT REPORT OF STAGE, SQUEEZE OR REMEDIAL CEMENT WORK	
*submit cbl and cement job summaries	
Method used	Cementing tool setting/perf depth
Cement volume	Cement top
Cement bottom	Date
<input type="checkbox"/> RECLAMATION: Attach technical page describing final reclamation procedures per Rule 1004.	
Final reclamation will commence on approximately	
<input type="checkbox"/> Final reclamation is completed and site is ready for inspection.	

## Technical Engineering/Environmental Notice

<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Report of Work Done	
Approximate Start Date: 11/20/12	Date Work Completed:	
Details of work must be described in full on Technical Information Page (Page 2 must be submitted.)		
<input type="checkbox"/> Intent to Recomplete (submit form 2)	<input type="checkbox"/> Request to Vent or Flare	<input type="checkbox"/> E&P Waste Disposal
<input type="checkbox"/> Change Drilling Plans	<input type="checkbox"/> Repair Well	<input type="checkbox"/> Beneficial Reuse of E&P Waste
<input type="checkbox"/> Gross Interval Changed?	<input type="checkbox"/> Rule 502 variance requested	<input type="checkbox"/> Status Update/Change of Remediation Plans
<input type="checkbox"/> Casing/Cementing Program Change	<input checked="" type="checkbox"/> Other: Water Shut Off	for Spills and Releases

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct and complete.

Signed: Greg Davis Date: 11/6/12 Email: greg.l.davis@wpxenergy.com  
Print Name: Greg Davis Title: Supervisor Permits  
COGCC Approved: [Signature] Title: NWAE Date: 11/7/12  
CONDITIONS OF APPROVAL, IF ANY:

TECHNICAL INFORMATION PAGE



FOR OGCC USE ONLY



1. OGCC Operator Number: 96850 API Number: 05-045-10236-00  
2. Name of Operator: WPX Energy Rocky Mountain, LLC OGCC Facility ID #             
3. Well/Facility Name: Williams Well/Facility Number: GM 414-27  
4. Location (QtrQtr, Sec, Twp, Rng, Meridian): SWSW Section 27-T6S-R96W 6th PM

This form is to be completed whenever a Sundry Notice is submitted requiring detailed report of work to be performed or completed. This form shall be transmitted within 30 days of work completed as a "subsequent" report and must accompany Form 4, page 1.

5. DESCRIBE PROPOSED OR COMPLETED OPERATIONS



Exploration and Production  
Water Squeeze Procedure

Wellname: **GM 414-27**  
Location: **SWSW 27 6S 96W**  
Field: **Grand Valley**  
API: **05-045-10236**

Surface Casing:	9-5/8" 32.3# set @ 1,116-ft
	4-1/2" 11.6# set @ 7,031-ft
Production Casing:	7,018-ft
PBTD:	3,493-ft
TOC:	2-3/8" tbg @ 6,560-ft
Tubing:	MV/Cameo (6,562 - 6,921 ft)
MV Completions:	RMWS CBL - 12/08/04
Correlate Log:	

Purpose: Identify and isolate high water producing zone

Proposed Procedure:

- 1 POOH w/ 2-3/8" tbg
- 2 RIH set RBP and packer and identify high water producing zone
- 3 POOH w/ packer and tubing
- 4 RIH and remediate high water producing zone with Class G cement
- 5 POOH w/ down hole equipment
- 6 Drill out cement and test to 500 psi
- 7 RIH with tubing and return to production
- 8 Submit subsequent report

Tony Franzone  
WPX Energy, Rocky Mountain, LLC  
Operations Engineer  
Mobile: 970 589 1454