

FORM

2

Rev  
12/05

## State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

400396749

Date Received:

05/20/2013

PluggingBond SuretyID

20130007

## APPLICATION FOR PERMIT TO:

1. ☒ Drill, ☐ Deepen, ☐ Re-enter, ☐ Recomplete and Operate

## 2. TYPE OF WELL

OIL ☒ GAS ☐ COALBED ☐ OTHER \_\_\_\_\_  
SINGLE ZONE ☒ MULTIPLE ☐ COMMINGLE ☐Refiling ☐Sidetrack ☒

3. Name of Operator: EE3 LLC

4. COGCC Operator Number: 10450

5. Address: 4410 ARAPAHOE AVENUE #100

City: BOULDER State: CO Zip: 80303

6. Contact Name: CLAYTON DOKE Phone: (303)216-0703 Fax: (303)216-2139

Email: cdoke@iptengineers.com

7. Well Name: DAMFINO Well Number: 2-06H

8. Unit Name (if appl): Unit Number:

9. Proposed Total Measured Depth: 7900

## WELL LOCATION INFORMATION

10. QtrQtr: SWSE Sec: 6 Twp: 6N Rng: 80W Meridian: 6

Latitude: 40.512603 Longitude: -106.416758

Footage at Surface: 398 feet FNL/FSL FSL 2017 feet FEL/FWL FEL

11. Field Name: UNNAMED Field Number: 85251

12. Ground Elevation: 8218 13. County: JACKSON

## 14. GPS Data:

Date of Measurement: 04/11/2013 PDOP Reading: 1.9 Instrument Operator's Name: UINTAH ENGINEERING &amp; LAND SURVEYING

15. If well is ☐ Directional ☐ Horizontal (highly deviated) submit deviated drilling plan.

Footage at Top of Prod Zone: FNL/FSL FEL/FWL Bottom Hole: FNL/FSL FEL/FWL

Sec: Twp: Rng: Sec: Twp: Rng:

16. Is location in a high density area? (Rule 603b)? ☐ Yes ☒ No

17. Distance to the nearest building, public road, above ground utility or railroad: 380 ft

18. Distance to nearest property line: 398 ft 19. Distance to nearest well permitted/completed in the same formation(BHL): 477 ft

## 20. LEASE, SPACING AND POOLING INFORMATION

Objective Formation(s)	Formation Code	Spacing Order Number(s)	Unit Acreage Assigned to Well	Unit Configuration (N/2, SE/4, etc.)
NIOBRARA	NBRR	531-1		

21. Mineral Ownership: ☐ Fee ☐ State ☒ Federal ☐ Indian Lease #: COC 6560022. Surface Ownership: ☐ Fee ☐ State ☒ Federal ☐ Indian23. Is the Surface Owner also the Mineral Owner? ☒ Yes ☐ No Surface Surety ID#:23a. If 23 is Yes: Is the Surface Owner(s) signature on the lease? ☐ Yes ☐ No

23b. If 23 is No: Surface Owners Agreement Attached or \$25,000 Blanket Surface Bond \$2,000 Surface Bond \$5,000 Surface Bond

24. Using standard QtrQtr, Sec, Twp, Rng format enter entire mineral lease description upon which this proposed wellsite is located (attach separate sheet/map if you prefer):

FEDERAL LEASE #COC065600: TOWNSHIP 6 NORTH, RANGE 80 WEST, 6TH; SECTION 6; LOTS 1 & 8, S/2NE, SE/4 & TOWNSHIP 6 NORTH, RANGE 80 WEST, 6TH; SECTION 7; N/2NW & SWNW & TOWNSHIP 6 NORTH, RANGE 80 WEST, 6TH; SECTION 5 W/2W/2.

25. Distance to Nearest Mineral Lease Line: 398 ft 26. Total Acres in Lease: 600

### DRILLING PLANS AND PROCEDURES

27. Is H2S anticipated? ☐ Yes ☒ No If Yes, attach contingency plan.

28. Will salt sections be encountered during drilling? ☐ Yes ☒ No

29. Will salt (>15,000 ppm TDS CL) or oil based muds be used during drilling? ☐ Yes ☒ No

30. If questions 28 or 29 are yes, is this location in a sensitive area (Rule 901.e)? ☐ Yes ☒ No

31. Mud disposal: ☐ Offsite ☒ Onsite

If 28, 29, or 30 are "Yes" a pit permit may be required.

Method: ☐ Land Farming ☐ Land Spreading ☐ Disposal Facility Other: Back fill and Cover

Note: The use of an earthen pit for Recompletion fluids requires a pit permit (Rule 905b). If air/gas drilling, notify local fire officials.

Casing Type	Size of Hole	Size of Casing	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Btm	Cmt Top
SURF	12+1/4	9+5/8	36	0	800	430	800	0
OPEN HOLE	8+3/4			800	7,900			

32. BOP Equipment Type: ☒ Annular Preventer ☒ Double Ram ☐ Rotating Head ☐ None

33. Comments No conductor casing will be run. The distance cited in question #17 is to an above ground utility to the Northwest, the distance to the nearest building is 1352' to the Northwest. All documents were executed under the previous operator of record, but were transferred along with the acreage pursuant to the purchase agreement already on file with the state (Doc #: 400395635). This well is a vertical pilot hole, its BHL is not within the legal setback from the offsetting lease line for order #531-2 and will not be completed or produced. This well is not listed as a re-file because the API is invalid; this well is a re-file of a well where the previous operator failed to file a Form 2 for the pilot hole. Cannot refile on an API that does not exist. This pilot hole has been assigned sidetrack 01 designation.

34. Location ID: 416625

35. Is this application in a Comprehensive Drilling Plan ? ☐ Yes ☒ No

36. Is this application part of submitted Oil and Gas Location Assessment ? ☒ Yes ☐ No

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: CLAYTON DOKE

Title: SENIOR ENGINEER Date: 5/20/2013 Email: cdoke@iptengineers.com

Based on the information provided herein, this Application for Permit-to-Drill complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: \_\_\_\_\_ Director of COGCC Date: \_\_\_\_\_

#### API NUMBER

05 057 06482 01

Permit Number: \_\_\_\_\_ Expiration Date: \_\_\_\_\_

#### CONDITIONS OF APPROVAL, IF ANY:

All representations, stipulations and conditions of approval stated in the Form 2A for this location shall constitute representations, stipulations and conditions of approval for this Form 2 Permit-to-Drill and are enforceable to the same extent as all other representations, stipulations and conditions of approval stated in this Permit-to-Drill.

Date retrieval failed for the subreport 'IntPolicy\_MTO' located at: W:\testpub\Net\Report\policy\_mto.rdl. Please check th

### Attachment Check List

Att Doc Num	Name
400396749	FORM 2 SUBMITTED
400421193	WELL LOCATION PLAT

Total Attach: 2 Files

### General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Permit	Back to draft for correction to API: well was permitted originally as a HZ well. So... this pilot hole should be the 01 and the original 00 should be the lateral.	5/21/2013 9:00:55 AM

Total: 1 comment(s)

### BMP

<u>Type</u>	<u>Comment</u>

Total: 0 comment(s)