

COGCC Field Inspection Report

Doc # 663801244

RE: SKR 598-35AV-10 API 05-045-14406

Finding: 700 psi on braden. Bleed braden to 0

Corrective Action complete 07/26/2013

Braden pressure for this well was bleed to 0