



STATE OF  
COLORADO

Gintautas - DNR, I

received 07/14/2013  
NOAV 200130026

## RE: Backyard 34-34 NOAV 200130026 response

1 message

**Castro, David** <David.Castro@pxd.com>

Thu, Jul 14, 2011 at 1:10 PM

To: "Gintautas, Peter" <Peter.Gintautas@state.co.us>

Peter,

We were able to locate sample results for this spill, pit water results. This spill didn't hit live water and was absorbed into the soil.

David Castro

Environmental Coordinator - Rockies Asset Team

Pioneer Natural Resources USA, Inc.

1401 17th St. Suite 1200

Denver, CO 80202

(direct) 303-675-2666

(work cell) 303-862-0894

(fax) 303-294-1275

david.castro@pxd.com

---

**From:** Gintautas, Peter [mailto:[Peter.Gintautas@state.co.us](mailto:Peter.Gintautas@state.co.us)]

**Sent:** Wednesday, July 06, 2011 9:32 AM

**To:** Holland, Dave

**Subject:** Backyard 34-34 NOAV 200130026 response

Dave, the response indicate soil samples were collected in the spill path and that analytical results would be provided. To date no results of soil sampling in the spill path have been received.

Peter Gintautas, Ph.D.

Environmental Protection Specialist, SE Colorado

Colorado Oil and Gas Conservation Commission

[719-846-3091](tel:719-846-3091)

[719-679-1326](tel:719-679-1326) (cell)

[colorado.gov/cogcc](http://colorado.gov/cogcc)

[peter.gintautas@state.co.us](mailto:peter.gintautas@state.co.us)

---

Statement of Confidentiality:

This message may contain information that is privileged or confidential. If you receive this transmission in error, please notify the sender by reply e-mail and delete the message and any attachments.



**Backyard 34-34 NOAV Pit Water Results.doc.pdf**

100K