

STATE OF
COLORADOreceived 09/20/2012
Facility 274305

te.co.us>

RE: COGCC FIELD INSPECTION REPORT [Doc#663600189]

1 message

Castro, David <David.Castro@pxd.com>
To: "Gintautas, Peter" <Peter.Gintautas@state.co.us>

Thu, Sep 20, 2012 at 10:27 AM

Peter, we cannot find any evidence of a Tin Barn Tr pit ever existing on aerials going back to 2005, pre-spud. It may be possible they dug a pit for drilling and then backfilled it, or used the other pit for drilling.

David Castro

Environmental Coordinator - Rockies Asset Team

Pioneer Natural Resources USA, Inc.

1401 17th St. Suite 1200

Denver, CO 80202

(direct) 303-675-2666

(work cell) 303-862-0894

(fax) 303-294-1275

david.castro@pxd.com

From: COGCC Field Inspection Report [mailto:peter.gintautas@state.co.us]**Sent:** Wednesday, September 19, 2012 8:44 AM**To:** Castro, David; Hiss, Duane; Glinisty, Judy**Cc:** peter.gintautas@state.co.us**Subject:** COGCC FIELD INSPECTION REPORT [Doc#663600189]**Importance:** High

DEPARTMENT OF NATURAL RESOURCES

John W. Hickenlooper, Governor

1120 Lincoln St. Suite 801

Denver, CO 80203

Phone: (303) 894-2100

FAX: (303) 894-2109

www.cogcc.state.co.us

COGCC Field Inspection Report

ATTACHED REPORT HAS BEEN SUBMITTED TO COGCC DATABASE
BASED ON FIELD INSPECTION RESULTS.

**PLEASE REVIEW ENTIRE REPORT. UNSATISFACTORY ITEMS AND/OR
VIOLATIONS AND CORRECTIVE ACTION DATES ARE HIGHLIGHTED IN
RED.**

Statement of Confidentiality:

This message may contain information that is privileged or confidential. If you receive this transmission in error, please notify the sender by reply e-mail and delete the message and any attachments.