

Document Number:
2429781

Date Received:
08/13/2013

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

| | |
|--|-------------------------------------|
| OGCC Operator Number: <u>95620</u> | Contact Name: <u>STEVEN D JAMES</u> |
| Name of Operator: <u>WESTERN OPERATING COMPANY</u> | Phone: <u>(303) 893-2432</u> |
| Address: <u>518 17TH ST STE 200</u> | Fax: <u>(303) 629-5735</u> |
| City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u> | Email: <u>S.D.JAMES@ATT.NET</u> |
| For "Intent" 24 hour notice required, Name: <u>SCHURE, KYM</u> Tel: <u>(970) 520-3832</u> | |
| COGCC contact: Email: <u>kym.schure@state.co.us</u> | |

| | | |
|--|--|------------------------|
| API Number <u>05-121-06568-00</u> | Well Name: <u>BOBCAT D SAND UNIT</u> | Well Number: <u>21</u> |
| Location: QtrQtr: <u>SWSW</u> Section: <u>9</u> Township: <u>1S</u> Range: <u>56W</u> Meridian: <u>6</u> | County: <u>WASHINGTON</u> Federal, Indian or State Lease Number: _____ | |
| Field Name: <u>BOBCAT</u> | Field Number: <u>7045</u> | |

Notice of Intent to Abandon
 Subsequent Report of Abandonment

Only Complete the Following Background Information for Intent to Abandon

Latitude: 39.976260 Longitude: -103.664220

GPS Data:
Date of Measurement: 03/22/2006 PDOP Reading: 6.0 GPS Instrument Operator's Name: ALLISON HAINES

Reason for Abandonment:
 Dry
 Production for Sub-economic
 Mechanical Problems
 Other _____

Casing to be pulled:
 Yes
 No
 Estimated Depth: 4115

Fish in Hole:
 Yes
 No
 If yes, explain details below

Wellbore has Uncemented Casing leaks:
 Yes
 No
 If yes, explain details below

Details: _____

Current and Previously Abandoned Zones

| Formation | Perf. Top | Perf. Btm | Abandoned Date | Method of Isolation | Plug Depth |
|-----------|-----------|-----------|----------------|---------------------|------------|
| D SAND | 5160 | 5180 | | | |

Total: 1 zone(s)

Casing History

| Casing Type | Size of Hole | Size of Casing | Weight Per Foot | Setting Depth | Sacks Cement | Cement Bot | Cement Top | Status |
|-------------|--------------|----------------|-----------------|---------------|--------------|------------|------------|--------|
| SURF | 14+3/4 | 10+3/4 | 32.75 | 99 | 85 | 99 | 0 | |
| 1ST | 7+7/8 | 5+1/2 | 15.5 | 5,191 | 175 | 5,191 | 4,191 | CALC |

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 5110 with 2 sacks cmt on top. CIBP #2: Depth _____ with _____ sacks cmt on top.
 CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
 CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 40 sks cmt from 4115 ft. to 4015 ft. Plug Type: STUB PLUG Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
 Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
 Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
(Cast Iron Cement Retainer Depth)

Set 50 sacks half in. half out surface casing from 149 ft. to 49 ft. Plug Tagged:
 Set 15 sacks at surface
 Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No
 Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing Plugging Date: _____
 *Wireline Contractor: _____ *Cementing Contractor: _____
 Type of Cement and Additives Used: _____
 Flowline/Pipeline has been abandoned per Rule 1103 Yes No *ATTACH JOB SUMMARY

Technical Detail/Comments:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: STEVEN D JAMES
 Title: PRESIDENT Date: 8/9/2013 Email: S.D.JAMES@ATT.NET

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: SUTPHIN, DIRK Date: 12/3/2013

CONDITIONS OF APPROVAL, IF ANY: _____ Expiration Date: 6/2/2014

| COA Type | Description |
|----------|---|
| | 1) Provide 24 hour notice of MIRU to Kym Schure at 970-520-3832 or e-mail at Kym.Schure@state.co.us. 2) Tag shoe plug. 3) For surface plug cement from 50' to surface in casing and in annulus. |

Attachment Check List

Att Doc Num **Name**

| | |
|--|--|
| | |
|--|--|

Total Attach: 0 Files

General Comments

| <u>User Group</u> | <u>Comment</u> | <u>Comment Date</u> |
|-------------------|---|-------------------------|
| Engineer | Note COGCC changes to form. Well Info: entered estimated depth casing to be pulled 4115 same as bottom of proposed cement plug 4115-4065. Zones: Erased date abandoned and plug depth - due to n/a. Casing History: Completed missing info using records on file: wt/ft and sks cmt surface casing, sks cmt 5-1/2" casing, cement top 4191 status is calculated by operator - no cbl on file. Plugging procedure: Increased length/depth of proposed stub from 4115-4065 to 4115-4015, stub. Shoe plug from 99-49 to 149-49, tag. Increase surface plug sacks cement from 10 to 15 sks. | 12/3/2013 8:54:18 AM |
| Permit | Requested and received wellbore diagrams. dhs 11/20/13 | 8/14/2013 6:25:19 AM |

Total: 2 comment(s)