



DE	ET	OE	ES
Document Number: 400529337			
Date Received: 12/22/2013			

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.
 A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 10112 Contact Name: Eric Sappington
 Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC Phone: (918) 526-5565
 Address: 16000 DALLAS PARKWAY #875 Fax: _____
 City: DALLAS State: TX Zip: 75248- Email: regulatory@foundationenergy.com
For "Intent" 24 hour notice required, Name: JOHNSON, RANDELL Tel: (303) 655.7472
COGCC contact: Email: randell.johnson@state.co.us

API Number 05-123-09104-00 Well Number: 4
 Well Name: PURITAN
 Location: QtrQtr: NWSE Section: 34 Township: 2N Range: 68W Meridian: 6
 County: WELD Federal, Indian or State Lease Number: _____
 Field Name: SPINDLE Field Number: 77900

Notice of Intent to Abandon Subsequent Report of Abandonment

Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.093090 Longitude: -104.987010
 GPS Data:
 Date of Measurement: 01/23/2010 PDOP Reading: 1.4 GPS Instrument Operator's Name: Joseph Collins
 Reason for Abandonment: Dry Production for Sub-economic Mechanical Problems
 Other _____
 Casing to be pulled: Yes No Estimated Depth: 3500
 Fish in Hole: Yes No If yes, explain details below
 Wellbore has Uncemented Casing leaks: Yes No If yes, explain details below
 Details: _____

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
SHANNON	5040	5052			
SUSSEX	4587	4600			
Total: 2 zone(s)					

Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
SURF	12+1/4	8+5/8	23	444	400	444	0	VISU
1ST	7+7/8	4+1/2	10.5	5,189	300	5,189	3,688	CALC

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 4537 with 2 sacks cmt on top. CIPB #2: Depth _____ with _____ sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIPB #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 45 sks cmt from 3400 ft. to 3550 ft. Plug Type: STUB PLUG Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
(Cast Iron Cement Retainer Depth)
Set 57 sacks half in. half out surface casing from 394 ft. to 544 ft. Plug Tagged:
Set 41 sacks at surface
Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No
Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing Plugging Date: _____
*Wireline Contractor: _____ *Cementing Contractor: _____
Type of Cement and Additives Used: _____
Flowline/Pipeline has been abandoned per Rule 1103 Yes No *ATTACH JOB SUMMARY

Technical Detail/Comments:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Rachel Eisterhold
Title: D&C/ HSE Assistant Date: 12/22/2013 Email: regulatory@foundationenergy.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: SCHLAGENHAUF, MARK Date: 12/27/2013

CONDITIONS OF APPROVAL, IF ANY: _____

Expiration Date: 6/26/2014

COA Type

Description

COA Type	Description
	Note changes in plugging procedure: 1) Submit Form 42 electronically to COGCC 48 hours prior to MIRU. 2) If unable to pull casing, contact COGCC for plugging modifications. 3) Leave at least 100' cement in the wellbore for each plug. 4) For 544' plug: pump plug and displace, shut-in, WOC 4 hours and tag plug – must be 394' or shallower. Adjust cement volumes accordingly. 5) Properly abandon flowlines as per Rule 1103. Once properly abandoned file electronic form 42.

Attachment Check List

<u>Att Doc Num</u>	<u>Name</u>
400529337	FORM 6 INTENT SUBMITTED
400531160	WELLBORE DIAGRAM
400531161	WELLBORE DIAGRAM

Total Attach: 3 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Permit	Well completion report dated 09/15/1977. Changed submitted by Name to Rachel Eisterhold per operator.	12/24/2013 2:26:02 PM

Total: 1 comment(s)