

From: [Finn Whiting](#)
To: Arthur.Koepsell@state.co.us
Cc: ["Kris Rowe"](#)
Subject: EDD Data Submittal
Date: Wednesday, January 22, 2014 5:39:09 PM

Mr. Koepsell,

As per our conversation this morning I am providing information regarding EDD submittals with incorrect well API's that need to be revised.

The samples were for the 609 Rule, therefore there are four (4) wells with separate data which need to be revised. Information for the individual wells is as follows:

- 1- Facility ID: 753049
Facility Name: Collins 112006
Sample ID: 535711

Wells which were incorrectly attached (and need removal) are as follows:

McLin B19 API: 045-19373
McLin B12 API: 045-19385
McLin B10 API: 045-19386
McLin B8 API: 045-19387
McLin B18 API: 045-19391

Correct wells which need to be attached are as follows:

McLin B20 API:045-19383
McLin B11 API:045-19380
McLin B17 API:045-19381
McLin B16 API:045-19384
McLin B15 API:045-19382

- 2- Facility ID: 753050
Facility Name: Frie 111062
Sample ID: 535707

Wells which were incorrectly attached (and need removal) are as follows:

McLin B19 API: 045-19373
McLin B12 API: 045-19385
McLin B10 API: 045-19386
McLin B8 API: 045-19387
McLin B18 API: 045-19391

Correct wells which need to be attached are as follows:

McLin B20 API:045-19383
McLin B11 API:045-19380

McLin B17 API:045-19381
McLin B16 API:045-19384
McLin B15 API:045-19382

- 3- Facility ID: 753051
Facility Name: Wallen 121626
Sample ID: 535702

Wells which were incorrectly attached (and need removal) are as follows:

McLin B19 API: 045-19373
McLin B12 API: 045-19385
McLin B10 API: 045-19386
McLin B8 API: 045-19387
McLin B18 API: 045-19391

Correct wells which need to be attached are as follows:

McLin B20 API:045-19383
McLin B11 API:045-19380
McLin B17 API:045-19381
McLin B16 API:045-19384
McLin B15 API:045-19382

- 4- Facility ID: 753048
Facility Name: Padia SENE 12 6S 92W
Sample ID: 535704

Wells which were incorrectly attached (and need removal) are as follows:

McLin B19 API: 045-19373
McLin B12 API: 045-19385
McLin B10 API: 045-19386
McLin B8 API: 045-19387
McLin B18 API: 045-19391

Correct wells which need to be attached are as follows:

McLin B20 API:045-19383
McLin B11 API:045-19380
McLin B17 API:045-19381
McLin B16 API:045-19384
McLin B15 API:045-19382

Please let me know if additional information is required for you to revise the sample data. I am available via cell at (970) 394-0702.

Thanks for your help!

Sincerely,
Finn Whiting

Finn Whiting
HRL Compliance Solutions, Inc.
Geologist
O: 970-243-3271
F: 970-243-3280
M: 970-394-0702
fwhiting@hrlcomp.com



This e-mail and any attachments are confidential and only for the use as authorized by HRL Compliance Solutions Inc. If you receive this message in error or are not the intended recipient, you should not retain, distribute, disclose or use any of this information. Permanently delete the e-mail and any attachments or copies.