

**From:** [Craig Burger - DNR](#)  
**To:** ["linn\\_wilson@sisna.com"](mailto:linn_wilson@sisna.com)  
**Cc:** [Christopher Kester - DNR](#)  
**Subject:** FEDERAL 1-15-8-101 (API # 077-08830)  
**Date:** Thursday, April 10, 2014 2:41:00 PM

---

Linn,

We sent you an inspection report (document #663801134 dated 6/14/2013) requiring a mechanical integrity test and a sundry to maintain the status of this non producing well.

We have a note in our well file that we requested a Form 5 (drilling completion report) for this well on 7/23/2013.

The limited information in our files indicates this well was never completed and the status should be WO (waiting on completion). Rule 326.b that requires a mechanical integrity test may not apply.

However, we are requiring a mechanical integrity test on this well per rule 207.a.

To update our well file and avoid enforcement, please complete the following by July 10, 2014:

- 1) Submit a form 5 (drilling completion report). A form 5A (completed interval report) should also be submitted if applicable.
- 2) Submit a sundry – technical engineering notice of intent to perform work and a description of the work.
- 3) Perform a mechanical integrity test on the well or plug and abandon the well (approved Form 6 NOI required prior to plugging).

Please call or respond if you have any questions or if you have additional information to provide us regarding this well.

Thank you,

Craig Burger  
Northwest Area Engineer



P 303.894.2100 x5687 | F 303.894.2109 | C 970-319-4194  
1120 Lincoln Street, Suite 801, Denver, CO 80203  
[craig\\_burger@state.co.us](mailto:craig_burger@state.co.us) | [www.colorado.gov/cogcc](http://www.colorado.gov/cogcc)