

FORM
6
Rev
12/05

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
Document Number: 400584083			
Date Received: 04/11/2014			

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 8960 Contact Name: Stephen Wolfe
 Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY Phone: (720) 440-6100
 Address: 410 17TH STREET SUITE #1400 Fax: (720) 305-0804
 City: DENVER State: CO Zip: 80202 Email: Swolfe@bonanzacrck.com

For "Intent" 24 hour notice required, Name: Waldron, Emily Tel: (970) 819-9609
COGCC contact: Email: emily.waldron@state.co.us

API Number 05-057-06394-00 Well Number: 144
 Well Name: MCCALLUM
 Location: QtrQtr: SESW Section: 2 Township: 9N Range: 79W Meridian: 6
 County: JACKSON Federal, Indian or State Lease Number: D028963
 Field Name: MCCALLUM Field Number: 53300

Notice of Intent to Abandon Subsequent Report of Abandonment

Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.776030 Longitude: -106.237030
 GPS Data:
 Date of Measurement: 09/18/2006 PDOP Reading: 2.0 GPS Instrument Operator's Name: Larry Robbins
 Reason for Abandonment: Dry Production for Sub-economic Mechanical Problems
 Other _____
 Casing to be pulled: Yes No Estimated Depth: _____
 Fish in Hole: Yes No If yes, explain details below
 Wellbore has Uncemented Casing leaks: Yes No If yes, explain details below
 Details: Packer stuckk in perms. HIC located above TOC(516')

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
PIERRE B	1130	1150			

Total: 1 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
SURF	11	8+5/8	24	163	75	163	0	VISU
1ST	7+7/8	5+1/2	15.5	1,297	120	1,310	516	CBL

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 1100 with 2 sacks cmt on top. CIBP #2: Depth _____ with _____ sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:

Perforate and squeeze at 250 ft. with 100 sacks. Leave at least 100 ft. in casing _____ CICR Depth
Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
(Cast Iron Cement Retainer Depth)

Set _____ sacks half in. half out surface casing from _____ ft. to _____ ft. Plug Tagged:

Set _____ sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing Plugging Date: _____

*Wireline Contractor: _____ *Cementing Contractor: _____

Type of Cement and Additives Used: _____

Flowline/Pipeline has been abandoned per Rule 1103 Yes No *ATTACH JOB SUMMARY

Technical Detail/Comments:

CBL on COGCC website already. Doc No. 1095523

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Stephen R. Wolfe

Title: Sr Prod Engr Date: 4/11/2014 Email: swolfe@bonanzacrk.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: ANDREWS, DAVID Date: 4/18/2014

CONDITIONS OF APPROVAL, IF ANY: _____ Expiration Date: 10/17/2014

COA Type

Description

1) Provide 48 hour notice of plugging MIRU via electronic Form 42.
2) Properly abandon flowlines per Rule 1103. File electronic Form 42 when flowline abandonment is complete.

Attachment Check List

<u>Att Doc Num</u>	<u>Name</u>
2167734	WELLBORE DIAGRAM
400584083	FORM 6 INTENT SUBMITTED

Total Attach: 2 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Permit	Attached WellBore Diagrams (before and after), and proposed procedure as per opr.	4/18/2014 2:36:44 PM
Engineer	Missing wellbore diagrams. Notified Permitting on 4/17/2014 and pushed this form to ON HOLD.	4/17/2014 5:19:22 PM

Total: 2 comment(s)