

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
Document Number: 400597801			
Date Received: 04/28/2014			

SUNDRY NOTICE

Submit a signed original. This form is to be used for general, technical and environmental sundry information. For proposed or completed operations, describe in full in Comments or provide as an attachment. Identify Well by API Number; identify Oil and Gas Location by Location ID Number; identify other Facility by Facility ID Number.

OGCC Operator Number: 47120 Contact Name Cheryl Light
 Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP Phone: (720) 929-6461
 Address: P O BOX 173779 Fax: (720) 929-7461
 City: DENVER State: CO Zip: 80217-3779 Email: cheryl.light@anadarko.com

Complete the Attachment
Checklist

OP OGCC

API Number : 05- 123 23679 00 OGCC Facility ID Number: 283705
 Well/Facility Name: SARCHET Well/Facility Number: 41-23
 Location QtrQtr: SENE Section: 23 Township: 3N Range: 66W Meridian: 6
 County: WELD Field Name: WATTENBERG
 Federal, Indian or State Lease Number: _____

Survey Plat		
Directional Survey		
Srvc Eqpmt Diagram		
Technical Info Page		
Other		

CHANGE OF LOCATION OR AS BUILT GPS REPORT

- Change of Location * As-Built GPS Location Report As-Built GPS Location Report with Survey

* Well location change requires new plat. A substantive surface location change may require new Form 2A.

SURFACE LOCATION GPS DATA Data must be provided for Change of Surface Location and As Built Reports.

Latitude _____ PDOP Reading _____ Date of Measurement _____
 Longitude _____ GPS Instrument Operator's Name _____

LOCATION CHANGE (all measurements in Feet)

Well will be: _____ (Vertical, Directional, Horizontal)

Change of **Surface Footage From** Exterior Section Lines:

Change of **Surface Footage To** Exterior Section Lines:

Current **Surface Location From** QtrQtr SENE Sec 23

New **Surface Location To** QtrQtr _____ Sec _____

Change of **Top of Productive Zone Footage From** Exterior Section Lines:

Change of **Top of Productive Zone Footage To** Exterior Section Lines:

Current **Top of Productive Zone Location From** Sec 23

New **Top of Productive Zone Location To** Sec _____

Change of **Bottomhole Footage From** Exterior Section Lines:

Change of **Bottomhole Footage To** Exterior Section Lines:

Current **Bottomhole Location** Sec 23 Twp 3N Range 66W

New **Bottomhole Location** Sec _____ Twp _____ Range _____

Is location in High Density Area? _____

Distance, in feet, to nearest building _____, public road: _____, above ground utility: _____, railroad: _____,
 _____ property line: _____, lease line: _____, well in same formation: _____

Ground Elevation _____ feet Surface owner consultation date _____

FNL/FSL		FEL/FWL	
<u>1919</u>	<u>FNL</u>	<u>579</u>	<u>FEL</u>
_____	_____	_____	_____
Twp <u>3N</u>	Range <u>66W</u>	Meridian <u>6</u>	
Twp _____	Range _____	Meridian _____	
<u>1293</u>	<u>FNL</u>	<u>45</u>	<u>FEL</u>
_____	_____	_____	_____
Twp <u>3N</u>	Range <u>66W</u>		
Twp _____	Range _____		
<u>1293</u>	<u>FNL</u>	<u>45</u>	<u>FEL</u>
_____	_____	_____	_____

** attach deviated drilling plan

**

**

Comments:

ENGINEERING AND ENVIRONMENTAL WORK

NOTICE OF CONTINUED TEMPORARILY ABANDONED STATUS

Indicate why the well is temporarily abandoned and describe future plans for utilization in the COMMENTS box below or provide as an attachment, as required by Rule 319.b.(3).

Date well temporarily abandoned _____ Has Production Equipment been removed from site? _____

Mechanical Integrity Test (MIT) required if shut in longer than 2 years. Date of last MIT _____

SPUD DATE: _____

TECHNICAL ENGINEERING AND ENVIRONMENTAL WORK

Details of work must be described in full in the COMMENTS below or provided as an attachment.

NOTICE OF INTENT Approximate Start Date 05/05/2014

REPORT OF WORK DONE Date Work Completed _____

<input type="checkbox"/> Intent to Recomplete (Form 2 also required)	<input type="checkbox"/> Request to Vent or Flare	<input type="checkbox"/> E&P Waste Mangement Plan
<input type="checkbox"/> Change Drilling Plan	<input checked="" type="checkbox"/> Repair Well	<input type="checkbox"/> Beneficial Reuse of E&P Waste
<input type="checkbox"/> Gross Interval Change	<input type="checkbox"/> Rule 502 variance requested. Must provide detailed info regarding request.	
<input type="checkbox"/> Other _____	<input type="checkbox"/> Status Update/Change of Remediation Plans for Spills and Releases	

COMMENTS:

ANNULAR CEMENT:

- 1 Call Foreman or Lead Operator at least 24 hr prior to rig move. If not already completed, request that they catch and remove plunger, isolate production equipment and remove any automation equipment prior to the rig showing up. Install perimeter fence as needed.
- 2 MIRU slickline. Fish plunger from lubricator. RIH and pull the bumper spring and standing valve if necessary. RBIH with sinker bars and tag bottom. Report findings. PBTD (should be at 7623'). RDMO slickline.
- 3 Spot a minimum of 33 jts of 1-1/4", 2.3#, J-55 tubing for annular job. Prepare location for base beam rig.
- 4 MIRU WO rig and auxiliary equipment. Check pressures. ND tree and adapter flange, NU BOP.
- 5 PU landing joint. TIW valve on top and screw into the tbg hanger. Back out the lock down pins and pull up on tbg string to break any possible sand bridges, unseat landing joint and lay down. Do not exceed 80% of tubing tensile strength, or 24,400-lb. Clean out as necessary to 7623'.
- 6 MIRU EMI equipment. TOOH with 2-3/8", 4.7#, J-55 tbg. EMI tbg while standing back 236 joints. Lay down joints with wall loss or penetrations >35%. Replace joints as necessary. Note joint number and depth of tubing leak(s) on production equipment failure report in OpenWells. Clearly mark all junk (red band) tubing sent to yard.
- 7 MIRU wireline, NU lubricator and RIH with Gauge Ring to 3750', POOH.
- 8 RIH on wireline with CCL and 4-1/2" RBP. Set RBP at +/- 3700' (collars at 3682' and 3724') and POOH. Dump bail 2 sx of sand on top of RBP and POOH. Pressure test RBP to 1,000 psi for 15 minutes.
- 9 RIH with CCL-GR-CBL-VDL. Run from top of RBP (and 2 sx of sand) to surface. Send CBL to Tyler Davis (Tyler.Davis@anadarko.com) for review to verify cement/perforation plans. If cement is present to 1186', then remedial cement isn't necessary. ND lubricator. In addition to normal handling of logs/job summaries, email copies of all cement job logs/job summaries and invoices to rscDJVendors@anadarko.com within 24 hours of the completion of the job. Once cleared by Engineering, proceed with next step.
- 10 ND BOP. ND WH. Unland 4-1/2" casing. NU double entry flange.
- 11 PU 42 joints of 1-1/4", 2.3#. J-55 10rd IJ tubing and TIH outside 4-1/2" casing and open hole to 1300'. Circulate with biocide treated fresh water on TIH.
- 12 MIRU cementer. Prepare and pump freshwater spacer, 20 bbls sodium metasilicate, 180 sks Type III cement + 1/4#/sk cello flake, mixed at 14 ppg and 1.53 cu ft/sk. The cement is to be retarded for 80 degF for a six hour pump time. Design is for coverage from 1300' to 50' above the bottom of surface casing (655'), including 20% excess. PUH to trip out of the hole with 1-1/4" tubing and shut in well.
- 13 RD cementing services.
- 14 Reland 4-1/2" csg. ND double entry flange. NU WH. SDFN to WOC.
- 15 MIRU wireline services.
- 16 MIRU wire line and run CCL-GR-CBL-VDL from top of RBP (and 2 sx of sand) to surface. In addition to normal handling of logs/job summaries, email copies of all cement job logs/job summaries and invoices to rscDJVendors@anadarko.com within 24 hours of the completion of the job. RDMO wireline. Clear CBL with Evans engineering before proceeding.
- 17 NU BOPs. PU and TIH with 2-3/8" tbg and retrieving head. Circulate sand off of RBP. Release RBP at 3700' and set RBP at 7075' (collars located at 7050' and 7093').
- 18 Release tbg from RBP, pick up 1 joint above RBP, and circulate all gas out of the hole. Pumping water with biocide, pressure test RBP and production casing to 1,000 psi for 15 minutes. If pressure test passes, proceed; otherwise contact engineering.
- 19 Bleed off pressure and stack tubing on RBP so the top joint of tbg is below the BOP.
- 20 ND BOP.
- 21 Make sure the wellhead has a WHI 5,000 psi flanged tubing head complete with 5,000 psi casing valves. Be sure all wellhead equipment is rated to 5,000 psi.
- 22 NU BOP.
- Sarchet 41-23: Annular Remedial Cement
- 23 Sting into tubing string and pick up just above the RBP set at +/- 7,075'.

CASING AND CEMENTING CHANGES

Casing Type	Size	Of	/	Hole	Size	Of	/	Casing	Wt/Ft	Csg/LinTop	Setting Depth	Sacks of Cement	Cement Bottom	Cement Top

H2S REPORTING

Data Fields in this section are intended to document Sample and Location Data associated with the collection of a Gas Sample that is submitted for Laboratory Analysis.

Gas Analysis Report must be attached.

H2S Concentration: _____ in ppm (parts per million)

Date of Measurement or Sample Collection _____

Description of Sample Point:

Absolute Open Flow Potential _____ in CFPD (cubic feet per day)

Description of Release Potential and Duration (If flow is not open to the atmosphere, identify the duration in which the container or pipeline would likely be opened for servicing operations.):

--

Distance to nearest occupied residence, school, church, park, school bus stop, place of business, or other areas where the public could reasonably be expected to frequent: _____

Distance to nearest Federal, State, County, or municipal road or highway owned and principally maintained for public use: _____

COMMENTS:

--

Best Management Practices

No BMP/COA Type

Description

--	--

Operator Comments:

--

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Cheryl Light
 Title: Sr. Regulatory Analyst Email: DJRegulatory@anadarko.com Date: 4/28/2014

Based on the information provided herein, this Sundry Notice (Form 4) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: JENKINS, STEVE Date: 5/2/2014

CONDITIONS OF APPROVAL, IF ANY:

COA Type

Description

--	--

General Comments

User Group

Comment

Comment Date

--	--	--

Total: 0 comment(s)

Attachment Check List

Att Doc Num

Name

400597801	FORM 4 SUBMITTED
400597802	OPERATIONS SUMMARY

Total Attach: 2 Files