

FORM
17Rev
6/99

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE ET OE ES

Document Number:

2361904

BRADENHEAD TEST REPORT

Step 1. Record all tubing and casing pressures as found. Step 2. Sample now. If intermediate or surface casing pressure > 25 psi. In sensitive areas, 1 psi.
Step 3. Conduct Bradenhead test. Step 4. Conduct intermediate casing test. Step 5. Send report to BLM within 3 days and to OGCC within 10 days. Include wellbore diagram if not previously submitted or if wellbore configuration has changed since prior program. Attach gas and liquid analyses if sampled.

1. OGCC Operator Number: 26580 3. BLM Lease No: _____
2. Name of Operator: BURLINGTON RESOURCES OIL & GAS LP
4. API Number; 05-067-08846-00 5. Multiple completion? ☐ Yes ☐ No
6. Well Name: UTE 80 Number: 2B
7. Location (QtrQtr, Sec, Twp, Rng, Meridian): NWSE,14,32N,11W,N
8. County LA PLATA 9. Field Name: IGNACIO BLANCO
10. Minerals: ☐ Fee ☐ State ☐ Federal ☐ Indian

11. Date of Test: 06/02/2011

12. Well Status: ☐ Flowing
☐ Shut In ☐ Gas Lift
☐ Pumping ☐ Injection
☐ Clock/Intermitter
☒ Plunger Lift

13. Number of Casing Strings:
☐ Two ☒ Three ☐ Liner?

14. EXISTING PRESSURES

Record all pressures as found	Tubing: _____ Fm: _____	Tubing: 49 Fm: _____	Prod Csg 79 Fm: _____	Intermediate Csg: 121	Surf. Csg 2
-------------------------------	----------------------------	-------------------------	--------------------------	--------------------------	----------------

BRADENHEAD TEST

Buried valve? ☒ Yes ☐ NoConfirmed open? ☒ Yes ☐ No

With gauges monitoring production, intermediate casing and tubing pressures, open surface casing (bradenhead) valve (if no intermediate casing, monitor only the production casing and tubing pressures.) Record pressures at five minute intervals Define characteristics of flow in "Bradenhead Flow" column using letter designations below:

O = No Flow; C = Continuous; D = Down to 0; V = Vapor
H = Water H2O; M = Mud; W = Whisper; S = Surge; G = Gas

BRADENHEAD SAMPLE TAKEN?

☐ Yes ☒ No ☐ Gas ☐ Liquid
Character of Bradenhead fluid: ☐ Clear ☐ Fresh
☐ Sulfur ☐ Salty ☐ Black

Other:(describe)

Sample cylinder number:

Elapsed Time (Min:Sec)	Fm: Tubing	Fm: Tubing:	Prod Csg PSIG	Intermedia Csg PSIG	Bradenhead Flow:
00:00	<input type="checkbox"/>	<input type="checkbox"/> 50	<input type="checkbox"/> 79	121	D
05:00	<input type="checkbox"/>	<input type="checkbox"/> 59	<input type="checkbox"/> 79	121	O
10:00	<input type="checkbox"/>	<input type="checkbox"/> 64	<input type="checkbox"/> 79	121	O
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		

Instantaneous Bradenhead PSIG at end of test: > 0

INTERMEDIATE CASING TEST

Buried valve? ☒ Yes ☐ NoConfirmed open? ☒ Yes ☐ No

With gauges monitoring production, intermediate casing and tubing pressures, open the intermediate casing valve. Record pressures at five minute intervals Characterize flow in "Intermediate Flow" column using letter designations below:

O = No Flow; C = Continuous; D = Down to 0; V = Vapor
H = Water H2O; M = Mud; W = Whisper; S = Surge; G = Gas

INTERMEDIATE SAMPLE TAKEN?

☐ Yes ☒ No ☐ Gas ☐ Liquid
Character of Intermediate fluid: ☐ Clear ☐ Fresh
☐ Sulfur ☐ Salty ☐ Black

Other:(describe)

Sample cylinder number:

Elapsed Time (Min:Sec)	Fm: Tubing	Fm: Tubing:	Prod Csg PSIG	Intermedia Csg PSIG	Bradenhead Flow:
00:00	<input type="checkbox"/>	<input type="checkbox"/> 69	<input type="checkbox"/> 79		G
05:00	<input type="checkbox"/>	<input type="checkbox"/> 74	<input type="checkbox"/> 80		G
10:00	<input type="checkbox"/>	<input type="checkbox"/> 78	<input type="checkbox"/> 80		W
15:00	<input type="checkbox"/>	<input type="checkbox"/> 78	<input type="checkbox"/> 80		W
20:00	<input type="checkbox"/>	<input type="checkbox"/> 79	<input type="checkbox"/> 80		W
25:00	<input type="checkbox"/>	<input type="checkbox"/> 80	<input type="checkbox"/> 80		W
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		

Instantaneous Intermediate Casing PSIG at end of test: > 0

Comments:

BH HAD 2 PSI DOWN TO NOTHING IN 1 SEC. NOT ABLE TO GET SAMPLE.
INT HAD 121 PSI DOWN TO WHISPER IN 13 MIN. WHISPERED FOR ENTIRE TEST

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Test Performed By: UNKNOWN Title: TESTER Phone: (000) 0000000

Signed: UNKNOWN Title: TESTER Date: 6/2/2011

Witnessed By: _____ Title: _____ Agency: _____