

API: 057- 06492

06/18/2014

Site Inspection pictures (2 total)



Fencing down by cattle.



Cattle contributing to perimeter berm erosion.