



STATE OF  
COLORADO

Allison - DNR, Rick <rick.allison@state.co.us>

---

## DCP Midstream Spill/BN-39-18-4-1-2-1 (01-P-04-03129) pipeline

---

**GrajedaDeBabb, Patricia** <PGrajedaDeBabb@dcpmidstream.com>

Wed, Jun 25, 2014 at 9:40 AM

To: "Allison - DNR, Rick" <rick.allison@state.co.us>

Cc: "gmarquez@weldgov.com" <gmarquez@weldgov.com>, "Nicholson, Ryan" <RNicholson@dcpmidstream.com>, "Wood, Samuel" <SWood@dcpmidstream.com>, "Cole, Chandler E" <CECole@dcpmidstream.com>

Mr. Allison,

There was a pipeline release associated with the BN-39-18-4-1-2-1 (01-P-04-03129) pipeline. The release is located a mile South on CR 15 and CR 56. The GPS coordinates are 44 Degrees 23' 34 77" North and 104 Degrees 55' 34 68" West. The spill amount and material was approximately 1 barrel, of condensate. The release is controlled and remediation activities are set to take place as soon as possible. The cause of the spill was due to pipeline corrosion. Attached is the Form 19, which contains the initial information. Also, once DCP Midstream gets setup to use the eForm we can submit this in the system.

Additional information will be provided in the 10 day follow up report. Please contact me if you have any questions or comments.

Patricia Grajeda De Babb

Staff Engineer/Env Spec

DCP Midstream, LP

970.378.6361 Office

575.802.5228 Cell



---

**BN-39-18-4-1-2-1 Pipeline 06242014.pdf**

101K