



July 10, 2014

Colorado Oil & Gas Conservation Commission
The Chancery Building
1120 Lincoln Street, Suite 801
Denver, CO 80203

Attn: Mr. Matt Lepore, Director

RE: **Request for omission of open-hole logging**
Kiyota 4A-35H-O367, Kiyota 4B-35H-O367, Kiyota 4C-35H-O367, Kiyota 4D-35H-O367, Kiyota 4E-35H-O367, Kiyota 4F-35H-O367, Kiyota 4G-35H-O367, Kiyota 4H-35H-O367, Kiyota 4I-35H-O367, Kiyota 4J-35H-O367, Kiyota 4K-35H-O367, Kiyota 4L-35H-O367
SWSE-Sec.35-T3N-R67W
Weld County, Colorado

Dear Mr. Lepore,

Please let this letter serve as a request for a Rule 317.o Exception for the proposed wells listed above. Rule 317.o requires logging all wells with a minimum of a resistivity log with gamma ray to adequately describe the stratigraphy and open hole logs to adequately verify the setting depth of surface casing and aquifer coverage.

Encana has identified the Kiyota 34-35 well as being in close enough proximity and as having acceptable logs to adequately describe the stratigraphy of the wellbores of the wells proposed on this multi-well pad.

| Well Name | API # | Log Type | Document # | SHL to SHL |
|--------------|-----------|---------------|------------|------------|
| Kiyota 34-35 | 123-19727 | Induction Log | 1014986 | 500' |

All these wells will have a cement bond log with gamma ray run from the intermediate casing shoe, or as close as possible, to above surface casing shoe to verify the setting depth of surface casing and aquifer coverage.

The horizontal portion of the all these wells will be logged while drilling with a gamma ray tool.

Encana requests approval of an exception to not run any open-hole logs in the vertical and directional build portion and not run a resistivity log in the horizontal portion of these wells.

Encana will report and submit all logs run on the Form 5 for every well.

Thank you for your assistance in this matter.

Sincerely,
ENCANA OIL & GAS (USA) INC.

Bonnie Lamond
Regulatory Analyst