



Bison Oil Well Cementing Plug & Abandon

Customer
Well Name

EXCELL SERVICES LLC
GELVIN 12-18-1S-44W

INVOICE #
LOCATION
FOREMAN
Date

13012
YUMA
AARON CARRASCO
7/29/2014

Treatment Report Page 2

DESCRIPTION OF JOB EVENTS

Safety Meeting MIRU	9:40AM		Displace 1			Displace 2			Displace 3			Displace 4		
	8AM		BBLS	Time	PSI	BBLS	Time	PSI	BBLS	Time	PSI	BBLS	Time	PSI
			0	9:50AM	30	0	11:11AM	10	0	11:32AM	10	0		
	9:45AM		10	9:53M	60	3.5	11:13AM	10				10		
	11:03AM		15	9:55AM	80	20			20			20		
	11:29AM		30			30			30			30		
			40			40			40			40		
M & P			50			50			50			50		
First Plug	Time Sacks		60			60			60			60		
	9:47AM	35	70			70			70			70		
	11:05am	35	80			80			80			80		
	11:30am	10	90			90			90			90		
		0	100			100			100			100		
	Mixed bbls		110			110			110			110		
	3.5		120			120			120			120		
Second Plug	3.5	130			130			130			130			
Third Plug	1	140			140			140			140			
Fourth Plug		150			150			150			150			
Water Temp	69													

Notes:

CEMENT TYPE 50/50 POZ 3% CCA 15.2 LBS/GAL=1.07 YIELD =4.20 GAL/SX .25% 810-cel

1ST PLUG @2287 FT-2112 FT MIXED & PUMPED 35 SX DISPLACED 15 BBLS

2ND PLUG @564FT-389 FT MIXED & PUMPED 35 SX DISPLACED 3.5 BBLS

3RD PLUG @60FT-13 FT MIXED & PUMPED 10 SX DISPLACED 1/4 BBLS

X

Work Performed

X Drilling Foreman
Title

X

Date

7-29-14