



# Bison Oil Well Cementing Plug & Abandon

Customer  
Well Name

EXCELL SERVICES LLC
LIPPERT 24-01-1S-45W

INVOICE #  
LOCATION  
FOREMAN  
Date

13016
YUMA
AARON CARRASCO
8/3/2014

Treatment Report Page 2

## DESCRIPTION OF JOB EVENTS

DESCRIPTION OF JOB EVENTS														
Safety Meeting MIRU	9:30am		Displace 1			Displace 2			Displace 3			Displace 4		
	8AM		BBLS	Time	PSI	BBLS	Time	PSI	BBLS	Time	PSI	BBLS	Time	PSI
			0	9:37AM	30	0	11:11AM	10	0	11:32AM	10	0		
	9:34AM		10	9:40AM	60	3.5	11:13AM	10	10-Jan			10		
	10:59am		14.5	9:42AM	80	20			20			20		
	11:30am		30			30			30			30		
			40			40			40			40		
M & P			50			50			50			50		
First Plug Second Plug Third Plug Fourth Plug Mixed bbls First Plug Second Plug Third Plug Fourth Plug Water Temp	Time Sacks		60			60			60			60		
	9:35am	35	70			70			70			70		
	11:01am	35	80			80			80			80		
	11:32am	10	90			90			90			90		
		#DIV/0!	100			100			100			100		
			110			110			110			110		
	3.5		120			120			120			120		
	3.5		130			130			130			130		
	1		140			140			140			140		
			150			150			150			150		
	69													

Notes:

CEMENT TYPE 50/50 POZ 3% CCA 15.2 LBS/GAL=1.07 YIELD =4.20 GAL/SX 25% flo-cel

1ST PLUG @2225 FT-2050 FT MIXED & PUMPED 35 SX DISPLACED 14.5 BBLS

2ND PLUG @532 FT-357 FT MIXED & PUMPED 35 SX DISPLACED 3.5 BBLS

3RD PLUG @62 FT-10 FT MIXED & PUMPED 10 SX DISPLACED 1/4 BBLS

X

*Just John*  
Work Performed

X *Drilling Foreman*  
Title

X *8-3-14*  
Date