

Site Photos (05-061-06365) 8/26/2014

Frazee 2-6 location API# 05-061-06365



Severe erosion on access road at location



Site Photos (05-061-06365) 8/26/2014

Erosion on access road looking towards the North at location



Erosion along access road going Southeast to the Frazee 2-6 location



Site Photos (05-061-06365) 8/26/2014

Looking South at the Frazee 2-6 location where equipment is being stored



Equipment storage near location looking North from location.



Site Photos (05-061-06365) 8/26/2014

Equipment storage near location



Vegetation growth inside of berms is a potential fire hazard

