

Site Photos (05-055-06314) 10/30/2014

Southeast corner of location facing North, SMU 4-23-L

photo #1



Berm around the South & East side of location

photo #2



Site Photos (05-055-06314) 10/30/2014

Cut face on the East side of location

photo #3



No slope stabilization present on the cut face, East side of location

photo #4



Site Photos (05-055-06314) 10/30/2014

South side of location

photo #5



Southwest corner of location. Erosion logs placed around the downhill side of the location photo #6



Site Photos (05-055-06314) 10/30/2014

Looking at the West side of the location. Topsoil appears to be at the base of the pad. photo #7



Tree/wood debris remains. Topsoil at the base of the pad.

photo #8



Site Photos (05-055-06314) 10/30/2014

Trees and stumps left on the West side of the pad location

photo #9



Trees and stumps left on the West side of the pad location

photo #10



Site Photos (05-055-06314) 10/30/2014

Topsoil pile at the base of the pad on West side of the location

photo #11



Erosion logs (8") around the pad and gravel pile

photo #12



Site Photos (05-055-06314) 10/30/2014

Gravel pile on North side of location, erosion logs (8") at the base

photo #13



Cattle guard to this location is damaged

photo #14

