

Session Report

1/22/2015

Information Panel

Name	Buffalo Location
Start Time	1/16/2015 2:27:06 PM
Stop Time	1/16/2015 2:43:08 PM
Device Name	BGN010013
Model Type	SoundPro DL
Device Firmware Rev	R.13F
Comments	No wind at tim of sound study. Sound study taken approx 25' from the NE corner of the complainants home.

Summary Data Panel

<u>Description</u>	<u>Meter</u>	<u>Value</u>	<u>Description</u>	<u>Meter</u>	<u>Value</u>
Leq	1	45.5 dB			
Exchange Rate	1	3 dB	Weighting	1	A
Response	1	SLOW	Bandwidth	1	OFF
Leq	2	65 dB			
Exchange Rate	2	3 dB	Weighting	2	C
Response	2	SLOW			

Calibration History

<u>Date</u>	<u>Calibration Action</u>	<u>Level</u>	<u>Cal. Model Type</u>	<u>Serial Number</u>	<u>Cert. Due Date</u>
1/16/2015 2:26:26 PM	Calibration	114.0			
1/16/2015 2:43:34 PM	Verification	113.9			

Logged Data Chart

Buffalo Location: Logged Data Chart

