

WPX Energy

GM 269-3

Location # 324067

Battery sign



Erosion rills behind tank and separator



Sediment trap needs cleaned out.



Traffic damage to ditches

