

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

400808788

Date Received:

03/13/2015

Spill report taken by:

ALLISON, RICK

Spill/Release Point ID:

441077

SPILL/RELEASE REPORT (SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Any spill or release which may impact waters of the State must be reported as soon as practicable; any spill over 20 bbls must be reported within 24 hours and all spills over five bbls must be reported within ten days. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

OPERATOR INFORMATION

Name of Operator: <u>EOG RESOURCES INC</u>	Operator No: <u>27742</u>	<b>Phone Numbers</b>
Address: <u>600 17TH ST STE 1100N</u>		Phone: <u>(307) 2357124</u>
City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>		Mobile: <u>(307) 2516728</u>
Contact Person: <u>Steve Bugni</u>		Email: <u>steve_bugni@eogresources.com</u>

INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 400800646

Initial Report Date: 02/27/2015 Date of Discovery: 02/12/2015 Spill Type: Recent Spill

Spill/Release Point Location:

Location of Spill/Release: QTRQTR SESE SEC 19 TWP 11N RNG 62W MERIDIAN 6

Latitude: 40.903169 Longitude: -104.355661

Municipality (if within municipal boundaries): \_\_\_\_\_ County: WELD

Reference Location:

Facility Type: TANK BATTERY  Facility/Location ID No 421221  
 No Existing Facility or Location ID No.  
 Well API No. (Only if the reference facility is well) 05- -

Fluid(s) Spilled/Released (please answer Yes/No):

Was one (1) barrel or more spilled outside of berms or secondary containment? No

Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.

Were Five (5) barrels or more spilled? Yes

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): 0 Estimated Condensate Spill Volume(bbl): 0

Estimated Flow Back Fluid Spill Volume(bbl): 0 Estimated Produced Water Spill Volume(bbl): >=5 and <100

Estimated Other E&P Waste Spill Volume(bbl): 0 Estimated Drilling Fluid Spill Volume(bbl): 0

Specify: \_\_\_\_\_

Land Use:

Current Land Use: OTHER Other(Specify): Oil production - confined to well p

Weather Condition: Sunny, no precipitation

Surface Owner: FEE Other(Specify): \_\_\_\_\_

Check if impacted or threatened by spill/Release (please answer Yes/No to all that apply):

Waters of the State  Residence/Occupied Structure  Livestock  Public Byway  Surface Water Supply Area   
As defined in COGCC 100-Series Rules

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

A hole was discovered in a produced water tank. Produced water leaked under the tank, was confined to secondary containment and did not leave the EOG location. Describe immediate response (how stopped, contained & recovered): Immediately isolated and drained the tank. No emergency pits constructed. Extent will be determined by analytical sampling, visually, and olfactory senses. Soils will be sampled for BTEX, pH, EC, SAR, and ESP. Contaminated soils will be removed and disposed. Tank will be repaired and inspected.

List Agencies and Other Parties Notified:

### SPILL/RELEASE DETAIL REPORTS

#1	Supplemental Report Date:	03/13/2015		
<b>FLUIDS</b>	BBL's SPILLED	BBL's RECOVERED	Unknown	
OIL	0	0	<input type="checkbox"/>	
CONDENSATE	0	0	<input type="checkbox"/>	
PRODUCED WATER	20	0	<input type="checkbox"/>	
DRILLING FLUID	0	0	<input type="checkbox"/>	
FLOW BACK FLUID	0	0	<input type="checkbox"/>	
OTHER E&P WASTE	0	0	<input type="checkbox"/>	
specify: _____				
Was spill/release completely contained within berms or secondary containment? <u>YES</u> Was an Emergency Pit constructed? <u>NO</u>				
<i>Secondary containment, including walls &amp; floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.</i>				
<b>A Form 15 Pit Report shall be submitted within 30 calendar days after the construction of an emergency pit</b>				
Impacted Media (Check all that apply) <input checked="" type="checkbox"/> Soil <input type="checkbox"/> Groundwater <input type="checkbox"/> Surface Water <input type="checkbox"/> Dry Drainage Feature				
Surface Area Impacted:		Length of Impact (feet): <u>13</u>	Width of Impact (feet): <u>13</u>	
Depth of Impact (feet BGS): _____		Depth of Impact (inches BGS): _____		
How was extent determined?				
The hole was in the bottom of the produced water tank. Water leaked out under the tank, but no standing water was present in the containment. Initial soils samples were collected within 1 foot of the outside of the tank perimeter (12 foot diameter tank) where moist soils were found below the surface. Additional samples will be collected the week of March 16th to confirm the spill did not spread outward.				
Soil/Geology Description:				
Gravel on top of native soils. Native soils are silts/clays.				
Depth to Groundwater (feet BGS) <u>35</u>		Number Water Wells within 1/2 mile radius: <u>0</u>		
If less than 1 mile, distance in feet to nearest		Water Well _____ None <input checked="" type="checkbox"/>	Surface Water _____	None <input checked="" type="checkbox"/>
		Wetlands _____ None <input checked="" type="checkbox"/>	Springs _____	None <input checked="" type="checkbox"/>
		Livestock _____ None <input checked="" type="checkbox"/>	Occupied Building <u>1300</u>	None <input type="checkbox"/>
Additional Spill Details Not Provided Above:				
The produced water tank has been drained and isolated to prevent further leakage. Lat/Long of the tank are 40.902854, -104.355313. Verbal notification of the spill was provided on 2/13/2015 to COGCC. A Form 19 was also mailed to COGCC on 2/13/2015.				

### CORRECTIVE ACTIONS

#1 Supplemental Report Date: 03/13/2015

Cause of Spill (Check all that apply)  Human Error  Equipment Failure  Historical-Unknown  
 Other (specify) \_\_\_\_\_

Describe Incident & Root Cause (include specific equipment and point of failure)

A hole developed in the bottom of a 400 bbl capacity produced water tank, causing approximately 20 bbls produced water to leak out of the bottom of the tank.

Describe measures taken to prevent the problem(s) from reoccurring:

The leaking tank was immediately isolated and drained. The hole in the tank has been repaired. Analytical soils samples were collected on February 18th, 2015, for analysis for EC, SAR, ESP, GRO, and DRO. Additional samples will be collected the week of March 16th, 2015 to determine the outward extents of the contamination.

Volume of Soil Excavated (cubic yards): 0

Disposition of Excavated Soil (attach documentation)  Offsite Disposal  Onsite Treatment  
 Other (specify) \_\_\_\_\_

Volume of Impacted Ground Water Removed (bbls): 0

Volume of Impacted Surface Water Removed (bbls): 0

**REQUEST FOR CLOSURE**

**Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.**

Basis for Closure:  Corrective Actions Completed (documentation attached)  
 Work proceeding under an approved Form 27  
 Form 27 Remediation Project No: \_\_\_\_\_

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Steve Bugni  
 Title: Environmental Tech Date: 03/13/2015 Email: steve\_bugni@eogresources.com

<u>COA Type</u>	<u>Description</u>

**Attachment Check List**

<u>Att Doc Num</u>	<u>Name</u>
400808788	FORM 19 SUBMITTED

Total Attach: 1 Files

**General Comments**

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>

Total: 0 comment(s)