



May 18, 2015

Mr. Matt Lepore
Colorado Oil and Gas Conservation Commission
1120 Lincoln Street, Suite 801
Denver, CO 80203

Re: Request for Rule 317.p Exception (Open-Hole Logging Requirements)
Regnier Farms 1A-1L 19H-B268
NWNE Sec 19 T2N R68 Weld County, CO

Dear Mr. Lepore:

Please let this letter serve as a request for a Rule 317.p Exception for the proposed wells listed above. Rule 317.p requires logging all wells with a minimum of a resistivity log with gamma ray to adequately describe the stratigraphy and open-hole logs to adequately verify the setting depth of surface casing and aquifer coverage.

Encana is requesting to run a combination RST/CBL (reservoir saturation tool using pulsed neutron) cased hole log on the 7" casing of one of the first wells to be drilled on the pad from approximately 500' to 6500' MD.

There are two existing wells with Induction logs that are within 1500' of the proposed wells, and with a difference in bearing from the proposed wells of greater than 90°. See chart below.

Well	API	SHL	Distance from proposed wells	Bearing	Log on file Document No.
Williams 18-16	123-19113	990 FNL 900 FEL 182N68W	1270'	NE	Induction, #1044159
Regnier Farms B Unit 1	123-11570	990 FNL 990 FEL 192N68W	1188'	SE	Induction #959462

All of the captioned wells will have a cement bond log with gamma ray run from the intermediate casing shoe, or as close as possible, to above surface casing shoe to verify the setting depth of surface casing and aquifer coverage.

The horizontal portion of all subject wells will be logged while drilling with a gamma ray tool.

Encana will report and submit all logs run on the Form 5 for every well and report that alternative logs were run per Rule 317.p and identifying the well that was run with the alternative logs.

Thank you for your assistance with this matter. If you have any questions or comments, please contact me at 720-876-5845

Sincerely,
ENCANA OIL & GAS (USA) INC.

Toby Sachen

Encana Oil & Gas (USA) Inc.
Republic Plaza
370 – 17 Street, Suite 1700
Denver, Colorado
United States 80202
t 303.623.2300
f 303.623.2400
www.encana.com



Regulatory Analyst

Encana Oil & Gas (USA) Inc.

Republic Plaza
370 – 17 Street, Suite 1700
Denver, Colorado
United States 80202

t 303.623.2300
f 303.623.2400

www.encana.com