

**From:** [Craig Burger - DNR](#)  
**To:** ["Li, Ningning"](#); [David Andrews - DNR](#); [Andrew Stone - DNR](#); [Jay Krabacher](#)  
**Cc:** ["Weitzel, Bob"](#); ["Nelson, Lance"](#)  
**Subject:** RE: 9-11 Pad CBL requirements  
**Date:** Thursday, May 28, 2015 2:26:00 PM

---

COGCC Doc# 2597163

Ningning,

I believe this will meet the intent of our current rules 317.p and 308A.b.(2).A.

You do not need to run the CBL as deep as possible into the curve as long as the log will show a clear cement top. I would say if at least 100' of quality cement bond is apparent, the log has been run deep enough.

I will put this communication in the well files for this pad.

Thanks,

Craig Burger  
Northwest Area Engineer



P 970.625.2497 Ext.2 | F 970.625.5682 | C 970-319-4194  
796 Megan Ave., Suite 201, Rifle, CO 81650  
[craig\\_burger@state.co.us](mailto:craig_burger@state.co.us) | [www.colorado.gov/cogcc](http://www.colorado.gov/cogcc)

---

**From:** Li, Ningning [<mailto:Ningning.Li@blackhillscorp.com>]  
**Sent:** Thursday, May 28, 2015 2:05 PM  
**To:** 'Craig Burger - DNR'  
**Cc:** Weitzel, Bob; Nelson, Lance  
**Subject:** 9-11 Pad CBL requirements

Craig

As per our conversation; on the 9-11H Pad Blackhills will provide the cement report with the form 5 and a CBL run as deep as possible into the curve to give top of cement instead of a CBL all the way through the lateral.

Thank you!  
Ningning Li

---

This electronic message transmission contains information from Black Hills Corporation, its affiliate or subsidiary, which may be confidential or privileged. The information is intended to be for the use of the individual or entity named above. If you are not the intended recipient, be aware the disclosure, copying, distribution or use of the contents of this information is prohibited. If you received this electronic transmission in error, please reply to sender immediately; then delete this message without copying it or further reading.