



STATE OF
COLORADO

Treitz - DNR, Rebecca <rebecca.treitz@state.co.us>

Re: Woolley-Sosa-Becky doc no. 400746954

Noto - DNR, John <john.noto@state.co.us>

Tue, Jun 2, 2015 at 8:41 AM

To: "Treitz - DNR, Rebecca" <rebecca.treitz@state.co.us>

Rebecca,

Please place Encana's response to our flaring question on the 2A as a BMP. It looks like Encana has sufficiently answered our other questions. We should be able to pass this one unless I missed something.

John

On Tue, May 12, 2015 at 5:16 PM, Treitz - DNR, Rebecca <rebecca.treitz@state.co.us> wrote:

John,

Bonnie sent over a revised explanation of EnCana's flaring. Please let me know what you think.

----- Forwarded message -----

From: **Lamond, Bonnie** <Bonnie.Lamond@encana.com>

Date: Tue, May 12, 2015 at 11:14 AM

Subject: RE: Woolley-Sosa-Becky doc no. 400746954

To: "Treitz - DNR, Rebecca" <rebecca.treitz@state.co.us>

Hi Rebecca,

Please see the responses below. If you have any other questions, don't hesitate to call.

Best regards,

Bonnie Lamond

Regulatory Analyst

t 720.876.5156

c 303.250.9383

Encana Services Company Ltd.

encana.com

Encana Services Company Ltd. provides

operational, corporate, administrative and

advisory services to Encana Corporation

and its subsidiaries.

From: Treitz - DNR, Rebecca [<mailto:rebecca.treitz@state.co.us>]
Sent: Friday, May 01, 2015 2:30 PM
To: Lamond, Bonnie
Subject: Re: Woolley-Sosa-Becky doc no. 400746954

Bonnie,

COGCC has reviewed the BMPs for the facility and feels that public comment concerns have been addressed by the operator on the 2A. COGCC has a few more questions regarding this facility;

- Under facilities, there is a mention of the oil and water line and the gas will go to Kerr-McGee. Please include a description of the pipeline (if any) from the separator to the sales line. **The gas sales line runs through meters on each separator and into a common line (~8") that will run underground either in front or behind the separators to the KMG meter house.**
- Please provide a comment that can be added to the siting rationale about whether or not the mineral/surface owner also owns the Building Unit in the Buffer Zone. **The house directly east of the pad is the owned by the landowner.**
- With your concurrence, COGCC would like to put a COA on the Form 2A that states: Temporary flares used during drilling shall be either enclosed, shielded or strategically placed to mitigate light impacts to nearby residents. **Current Encana drilling operations into and through productive horizons are planned to keep a hydrostatic "over-balance" on the formation. Encana does not intentionally drill ahead with flares and in cases where we do have flares, they are intermittent and only kept for the amount of time it takes to raise our drilling fluid weight to be over-balanced again. In more extreme cases of Well Control Operations, it's possible to encounter a prolonged flare. This is required in order to bring operations back to normal and ensure proper safety of the rig/rig crews involved during this operation. These flaring instances are rare, but do occur. Encana typically has a good understanding of the pore pressures and will plan accordingly in order to help mitigate potential light impacts to nearby residents.**

Please let me know if you have any questions.

Thank you,
Rebecca

On Fri, Apr 24, 2015 at 2:38 PM, Lamond, Bonnie <Bonnie.Lamond@encana.com> wrote:

Hi Rebecca,

We are in the middle of gathering responses internally.

Best regards,

Bonnie Lamond

Regulatory Analyst

t 720.876.5156

c 303.250.9383

Encana Services Company Ltd.

encana.com

Encana Services Company Ltd. provides
operational, corporate, administrative and
advisory services to Encana Corporation
and its subsidiaries.

From: Treitz - DNR, Rebecca [mailto:rebecca.treitz@state.co.us]

Sent: Friday, April 24, 2015 12:44 PM

To: Lamond, Bonnie

Subject: Woolley-Sosa-Becky doc no. 400746954

Bonnie,

COGCC is trying to follow up on the Woolley-Sosa-Becky amended location. Did Encana respond to any of the public comments?

Thank you,

Rebecca

--

Rebecca Treitz

Oil and Gas Location Assessment Specialist

P [303.894.2100](tel:303.894.2100) x5173 | F [303.894.2109](tel:303.894.2109) |

1120 Lincoln Street, Suite 801, Denver, CO 80203

Rebecca.Treitz@state.co.us | www.colorado.gov/cogcc

This email communication and any files transmitted with it may contain confidential and or proprietary information and is provided for the use of the intended recipient only. Any review, retransmission or dissemination of this information by anyone other than the intended recipient is prohibited. If you receive this email in error, please contact the sender and delete this communication and any copies immediately. Thank you.

<http://www.encana.com>

--

Rebecca Treitz

Oil and Gas Location Assessment Specialist

P [303.894.2100](tel:303.894.2100) x5173 | F [303.894.2109](tel:303.894.2109) |

1120 Lincoln Street, Suite 801, Denver, CO 80203

Rebecca.Treitz@state.co.us | www.colorado.gov/cogcc

This email communication and any files transmitted with it may contain confidential and or proprietary information and is provided for the use of the intended recipient only. Any review, retransmission or dissemination of this information by anyone other than the intended recipient is prohibited. If you receive this email in error, please contact the sender and delete this communication and any copies immediately. Thank you.

<http://www.encana.com>

--

Rebecca Treitz

Oil and Gas Location Assessment Specialist

P [303.894.2100](tel:303.894.2100) x5173 | F [303.894.2109](tel:303.894.2109) |

1120 Lincoln Street, Suite 801, Denver, CO 80203

Rebecca.Treitz@state.co.us | www.colorado.gov/cogcc

John Noto P.G.

Oil and Gas Location Assessment Supervisor



P 303.894-2100 ext 5182 | C 720.498-5298

1120 Lincoln Street, Suite 801, Denver, CO 80203

john.noto@state.co.us | www.colorado.gov/cogcc