



REPORT OF UNDESIRABLE EVENT

NTL-3A (EFFECTIVE MARCH 1, 1979)

5-87-BCB#3
05-103-05657
Location # 314414

To: District Engineer BLM, Fluid Minerals Branch, P O Box 248, Craig, CO 81626
From: Chevron U.S.A. Inc., P. O. Box 599, Denver, Colorado 80201

1. Spill ☒ Discharge _____ Blowout _____ Accident _____ Fire or Explosion _____
2. BBLS Discharged: 48 bbls. NGL'S _____ BBLS Lost: -0-
3. Contained on location: Yes ☒ No _____
4. Date and time of event: 5/7/87 8:00 AM
5. Date and time reported to BLM: Not Required
6. Location of event: Near Fee 3, SW NW Sec. 29, T2N, R102W
Rangely Weber Sand Unit, Rio Blanco County, Colorado
7. Specific nature and cause of event

Leak in NGL product line caused by corroded line.

8. Describe resultant damage:

N/A

9. Time required for control of event: 15 min.
10. Action taken to control and contain:

Leak was contained in man made trench, sucked up and hauled away.

11. Action taken to prevent recurrence:-

Repaired line.

12. Cause of death:

N/A

13. Other agencies notified:

EPA VIII, Denver, CO -

COLO. DEPT. OF HEALTH, WTR QUALITY CONTROL, DENVER, CO -

COLO. OIL & GAS CONSV COMM, DENVER, CO - Written Report Only

14. Other pertinent information:

Signature

T.L. Hurst
T.L. HURST

Date

5/19/87

Title

Area Supervisor

** A COPY OF THIS FORM WAS MAILED TO EACH AGENCY LISTED IN PARAGRAPH 13 ABOVE.