



REPORT OF UNDESIRABLE EVENT
NTL-3A (EFFECTIVE MARCH 1, 1979)

To: District Engineer BLM, Bureau of Land Management, P. O. Box 248, Craig, CO 81626
From: Chevron U.S.A. Inc., P. O. Box 599, Denver, Colorado 80201

- 1. Spill Discharge _____ Blowout _____ Accident _____ Fire or Explosion _____
- 2. BBLS Discharged: 100 bbls. inj. water BBLS Lost: 100 bbls.
- 3. Contained on location: Yes No _____
- 4. Date and time of event: 10/31/87 11:00 PM
- 5. Date and time reported to U.S.G.S.: 11/02/87
- 6. Location of event: Near Rector 6X, NE NW Sec 3, R102W, T1N
- 7. Specific nature and cause of event
Split in injection line.
- 8. Describe resultant damage:
N/A
- 9. Time required for control of event: ± 15 minutes
- 10. Action taken to control and contain:
Valve closed. All water soaked into ground.
- 11. Action taken to prevent recurrence:
Replaced section of pipe.
- 12. Cause of death:
N/A

13. Other agencies notified:
Colorado Department of Health, Air Quality Control, Denver, Co.
Colorado Oil and Gas Conservation Commission, Denver, Co - Written Report Only

14. Other pertinent information:

Signature TL Hurst Date 11/6/87
T. L. Hurst
Title _____
Unit Supervisor