



02469032

2-87-BCB #8

REPORT OF UNDESIRABLE EVENT


NTL-3A (EFFECTIVE MARCH 1, 1979)

OS-103-66227

Location # 314618

To: District Engineer BLM, Fluid Minerals Branch, P O Box 248, Craig, CO 81626
From: Chevron U.S.A. Inc., P. O. Box 599, Denver, Colorado 80201

1. Spill ☒ Discharge _____ Blowout _____ Accident _____ Fire or Explosion _____
2. BBLS Discharged: 1000 Produced Water BBLS Lost: 200 Produced Water
3. Contained on location: Yes ☒ No _____
4. Date and time of event: 2/18/87 3:00 P.M.
5. Date and time reported to BLM: 2/19/87 10:30 AM
6. Location of event: 1000' SW of Fee 57, SESE, Sec. 28, T2N, R102W
Rangely Weber Sand Unit, Rio Blanco County, Colorado
7. Specific nature and cause of event
Internal corrosion caused pipe to rupture.
8. Describe resultant damage:
N/A
9. Time required for control of event: ± 30 minutes
10. Action taken to control and contain:
Built dike 500 yds down from leak, picked up water & hauled to Fee 10 pit.
Rest soaked into ground.
11. Action taken to prevent recurrence:-
Replaced section of line.
12. Cause of death:
N/A
13. Other agencies notified:
COLO. DEPT. OF HEALTH, WTR QUALITY CONTROL, DENVER, CO -
COLO. OIL & GAS CONSV COMM, DENVER, CO - Written Report Only
14. Other pertinent information:



Signature

T. L. Hurst

Date

3/6/87

T. L. Hurst, Area Supervisor

Title

Area Supervisor

** A COPY OF THIS FORM WAS MAILED TO EACH AGENCY LISTED IN PARAGRAPH 13 ABOVE.