



02469029

REPORT OF UNDESIRABLE EVENT
NTL-3A (EFFECTIVE MARCH 1, 1979)

1-#19-87-BCB
05-103-06087
Location # 314547


To: District Engineer BLM, Fluid Minerals Branch, P O Box 248, Craig, CO 81626
From: Chevron U.S.A. Inc., P. O. Box 599, Denver, Colorado 80201

- 1. Spill Discharge _____ Blowout _____ Accident _____ Fire or Explosion _____
- 2. BBLs Discharged: 1000 BBLs Lost: 20
- 3. Contained on location: Yes No _____
- 4. Date and time of event: 1-29-87 11: A.M.
- 5. Date and time reported to BLM: 1-30-87 9:57 A.M.
- 6. Location of event: 50 yds S of Carney Unit 1 SWNE Sec. 1, T1N R102W
Rangely Weber Sand Unit, Rio Blanco County, Colorado
- 7. Specific nature and cause of event

Corrosion inside water injection line caused leak.

- 8. Describe resultant damage:

N/A



- 9. Time required for control of event: ± 30 minutes

- 10. Action taken to control and contain:

Shut off valve, sucked up water & took to Fee 10 pit, except for 20 bbls soaked into ground.

- 11. Action taken to prevent recurrence:-

Repaired line.

- 12. Cause of death:

N/A

- 13. Other agencies notified:

~~XXXXXXXXXXXXXXXXXXXX~~

Pam Harley 1:40 P.M.

COLO. DEPT. OF HEALTH, WTR QUALITY CONTROL, DENVER, CO - Called & Written, 1-30-87

COLO. OIL & GAS CONSV COMM, DENVER, CO - Written Report Only - 2-2-87

- 14. Other pertinent information:

Signature T. L. Hurst Date 2/3/87
T. L. Hurst, Area Supervisor

Title Area Supervisor

** A COPY OF THIS FORM WAS MAILED TO EACH AGENCY LISTED IN PARAGRAPH 13 ABOVE.