


**Windy Hills 8-5/8" Intermediate 3-17D**  
**Henry Hollins 8-15-2007 SO# 5297505**



Local Event Log					
1	Start Job	8/14/2007 20:27:00	2	Pressure test lines to 3000 psi	8/14/2007 20:44:46
3	Start 30 bbls of water	8/14/2007 20:47:45	4	Start 60 bbls Mud Flush	8/14/2007 20:57:34
5	Start 30 bbls water	8/14/2007 21:17:38	6	Start 1116 bbls lead cement @ 11.1ppg	8/14/2007 21:27:50
7	Start 174 bbls tail @ 15.8ppg	8/15/2007 01:41:23	8	Shutdown/Drop Plug	8/15/2007 02:15:47
9	Start 10 bbls water	8/15/2007 02:17:41	10	Start 300 bbls Mud @ 10.1ppg	8/15/2007 02:19:57
11	Start lifting cement	8/15/2007 02:43:23	12	Lost returns	8/15/2007 02:58:09
13	Regained returns	8/15/2007 03:20:04	14	Start 19 bbls of Water	8/15/2007 03:31:47
15	Land Plug/Check Floats	8/15/2007 03:39:19	16	End Job	8/15/2007 03:47:37

