



02470174

05-103-05433

Loc# 314356

## REPORT OF UNDESIRABLE EVENT

2-5-87-BCB

NTL-3A (EFFECTIVE MARCH 1, 1979)

To: District Engineer BLM, Fluid Minerals Branch, P O Box 248, Craig, CO 81626  
From: Chevron U.S.A. Inc., P. O. Box 599, Denver, Colorado 80201

1. Spill X Discharge \_\_\_\_\_ Blowout \_\_\_\_\_ Accident \_\_\_\_\_ Fire or Explosion \_\_\_\_\_
2. BBLS Discharged: 200 bbls water BBLS Lost: 50 bbls
3. Contained on location: Yes X No \_\_\_\_\_
4. Date and time of event: 2-2-87 4:00 P.M.
5. Date and time reported to BLM: 2-4-87 2:50 P.M.
6. Location of event: SE/NW Sec. 2, T1N, R102W  
Rangely Weber Sand Unit, Rio Blanco County, Colorado
7. Specific nature and cause of event

Pressure split in line caused leak.

8. Describe resultant damage:

N/A

9. Time required for control of event: ± 30 minutes

10. Action taken to control and contain:

Shut valve in, water picked up and taken to Fee 10 Pit, except for  
50 bbls soaked in ground.

11. Action taken to prevent recurrence:

Replaced line.


12. Cause of death:

N/A

13. Other agencies notified:

[REDACTED] 2-4-87, 9:05 A.M.  
COLO. DEPT. OF HEALTH, WTR QUALITY CONTROL, DENVER, CO - Called & Written, Ned Noac  
COLO. OIL & GAS CONSV COMM, DENVER, CO - Written Report Only 2-5-87

14. Other pertinent information:



Signature

T. L. Hurst  
T. L. Hurst, Area Supervisor

Date

2/10/87

Title

COLO. OIL &amp; GAS CONSV. COMM.

\*\* A COPY OF THIS FORM WAS MAILED TO EACH AGENCY LISTED IN PARAGRAPH 13 ABOVE.