


FORM 6 Rev 12/05	State of Colorado Oil and Gas Conservation Commission 1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109				DE ET OE ES
	WELL ABANDONMENT REPORT				<b style="color: red;">Replug By Other Operator Document Number: <div style="text-align: center;">400766156</div> Date Received: <div style="text-align: center;">01/22/2015</div>
	<p><small>This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.</small></p> <p><small>A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.</small></p>				

OGCC Operator Number: <u>8960</u>	Contact Name: <u>Joel Dill</u>
Name of Operator: <u>BONANZA CREEK ENERGY OPERATING COMPANY</u>	Phone: <u>(720) 440-6100</u>
Address: <u>410 17TH STREET SUITE #1400</u>	Fax: <u>(720) 279-2331</u>
City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>	Email: <u>jdill@bonanzacrk.com</u>
For "Intent" 24 hour notice required, Name: _____ Tel: _____ COGCC contact: Email: _____	

API Number <u>05-123-10436-00</u>	Well Name: <u>PACKARD</u>	Well Number: <u>33-10</u>	
Location: QtrQtr: <u>NWSE</u> Section: <u>10</u> Township: <u>5N</u> Range: <u>61W</u> Meridian: <u>6</u>			
County: <u>WELD</u>	Federal, Indian or State Lease Number: _____		
Field Name: <u>WILDCAT</u>	Field Number: <u>99999</u>		

☐ Notice of Intent to Abandon
 ☒ Subsequent Report of Abandonment

<i>Only Complete the Following Background Information for Intent to Abandon</i>	
Latitude: <u>40.414100</u>	Longitude: <u>-104.192530</u>
GPS Data:	
Date of Measurement: <u>01/27/2014</u>	PDOP Reading: <u>1.8</u>
GPS Instrument Operator's Name: <u>Wyatt Hall</u>	
Reason for Abandonment: <input type="checkbox"/> Dry <input type="checkbox"/> Production for Sub-economic <input type="checkbox"/> Mechanical Problems <input type="checkbox"/> Other _____	
Casing to be pulled: <input type="checkbox"/> Yes <input type="checkbox"/> No	Estimated Depth: _____
Fish in Hole: <input type="checkbox"/> Yes <input type="checkbox"/> No	If yes, explain details below
Wellbore has Uncemented Casing leaks: <input type="checkbox"/> Yes <input type="checkbox"/> No	If yes, explain details below
Details: _____	

Current and Previously Abandoned Zones					
Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
NIOBRARA			08/26/2014	CEMENT	5745
Total: 1 zone(s)					

Casing History								
Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
SURF	12+1/4	8+5/8	24.00	184	200	184	0	VISU

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth _____ with _____ sacks cmt on top. CIPB #2: Depth _____ with _____ sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIPB #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set	100	sks cmt from	5945	ft. to	5745	ft.	Plug Type:	OPEN HOLE	Plug Tagged:	<input checked="" type="checkbox"/>
Set	450	sks cmt from	3400	ft. to	2826	ft.	Plug Type:	OPEN HOLE	Plug Tagged:	<input checked="" type="checkbox"/>
Set	275	sks cmt from	712	ft. to	0	ft.	Plug Type:	OPEN HOLE	Plug Tagged:	<input type="checkbox"/>
Set		sks cmt from		ft. to		ft.	Plug Type:		Plug Tagged:	<input type="checkbox"/>
Set		sks cmt from		ft. to		ft.	Plug Type:		Plug Tagged:	<input type="checkbox"/>

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

(Cast Iron Cement Retainer Depth)

Set _____ sacks half in. half out surface casing from _____ ft. to _____ ft. Plug Tagged: ☐

Set _____ sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☒ No

Set 0 sacks in rat hole Set 0 sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing

Plugging Date: 08/28/2014

*Wireline Contractor: N/A

*Cementing Contractor: Cementers Well Service, Inc.

Type of Cement and Additives Used: Class G

Flowline/Pipeline has been abandoned per Rule 1103 ☐ Yes ☐ No

*ATTACH JOB SUMMARY

Technical Detail/Comments:

Rat hole and mouse hole previously plugged.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____

Print Name: Christina Bright-Vernon

Title: Operations Assisitant

Date: 1/22/2015

Email: cbright-vernon@bonanzacrk.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: JENKINS, STEVE

Date: 8/13/2015

CONDITIONS OF APPROVAL, IF ANY:

COA Type

Description

--	--

Attachment Check List

<u>Att Doc Num</u>	<u>Name</u>
400766156	FORM 6 SUBSEQUENT SUBMITTED
400767832	WELLBORE DIAGRAM
400778585	CEMENT JOB SUMMARY

Total Attach: 3 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Permit	400628228 WELL ABANDONMENT REPORT (INTENT) 06/20/2014	4/17/2015 10:10:33 AM

Total: 1 comment(s)