



August 24, 2015

Mr. Matt Lepore
Colorado Oil and Gas Conservation Commission
1120 Lincoln Street, Suite 801
Denver, CO 80203

Re: Request for Rule 317.p Exception (Open-Hole Logging Requirements)

Well Name	Document #	Well Name	Document #
Woolley Becky 2A-7H-E168	400868290	Woolley Sosa 2A-7H-E168	400868357
Woolley Becky 2B-7H-E168	400868294	Woolley Sosa 2B-7H-E168	400868361
Woolley Becky 2D-7H-E168	400868318	Woolley Sosa 2D-7H-E168	400868373
Woolley Becky 2E-7H-E168	400868341	Woolley Sosa 2E-7H-E168	400868375
Woolley Becky 2F-7H-E168	400868342	Woolley Sosa 2F-7H-E168	400868376
Woolley Becky 2H-7H-E168	400868352		

SWNW Sec 7 T1N R68 Weld County, CO

Dear Mr. Lepore:

Please let this letter serve as a request for a Rule 317.p Exception for the proposed wells listed above. Rule 317.p requires logging all wells with a minimum of a resistivity log with gamma ray to adequately describe the stratigraphy and open-hole logs to adequately verify the setting depth of surface casing and aquifer coverage.

Encana is requesting to run a combination RST/CBL (reservoir saturation tool using pulsed neutron) cased hole log on the 7" casing of one of the first wells to be drilled on the pad from approximately 500' to 6500' MD.

Encana has identified an existing well with Induction logs that is within 750' of the proposed wells. See chart below.

Well	API	SHL	Avg. Distance from proposed wells	Bearing	Log on file Document No.
Woolley 12-7	123-22988	2117 FNL, 457 FWL, 7 1N 68W	150'	NW	Dual Induction, #1382518

All of the captioned wells will have a cement bond log with gamma ray run from the intermediate casing shoe, or as close as possible, to above surface casing shoe to verify the setting depth of surface casing and aquifer coverage.

The horizontal portion of all subject wells will be logged while drilling with a gamma ray tool.

The Form 5 for each well shall clearly state, "No open hole logs were run" and shall reference the Rule 317.p Exception granted for the well. The Form 5 for each well on the pad will identify the well that was logged with alternative logs by API number, well name and well number.

Thank you for your assistance with this matter. If you have any questions or comments, please contact me at 720-876-5845

Encana Oil & Gas (USA) Inc.
Republic Plaza
370 – 17 Street, Suite 1700
Denver, Colorado
United States 80202
t 303.623.2300
f 303.623.2400
www.encana.com



Sincerely,

A handwritten signature in black ink that reads "Toby Sachen". The signature is written in a cursive, flowing style.

Toby Sachen

Regulatory Analyst

ENCANA OIL & GAS (USA) INC.

Encana Oil & Gas (USA) Inc.

Republic Plaza
370 – 17 Street, Suite 1700
Denver, Colorado
United States 80202

t 303.623.2300
f 303.623.2400

www.encana.com