

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

400901422

Date Received:

09/18/2015

Spill report taken by:

GINTAUTAS, PETER

Spill/Release Point ID:

443194

SPILL/RELEASE REPORT (SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Any spill or release which may impact waters of the State must be reported as soon as practicable; any spill over 20 bbls must be reported within 24 hours and all spills over five bbls must be reported within ten days. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

OPERATOR INFORMATION

Name of Operator: <u>KERR MCGEE OIL & GAS ONSHORE LP</u>	Operator No: <u>47120</u>	Phone Numbers
Address: <u>P O BOX 173779</u>		Phone: <u>(970) 336-3500</u>
City: <u>DENVER</u>	State: <u>CO</u>	Mobile: <u>(970) 515-1238</u>
Zip: <u>80217-3779</u>		Email: <u>Sam.LaRue@anadarko.com</u>
Contact Person: <u>Sam LaRue</u>		

INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 400898373

Initial Report Date: 09/11/2015 Date of Discovery: 09/10/2015 Spill Type: Recent Spill

Spill/Release Point Location:

Location of Spill/Release: QTRQTR NESE SEC 33 TWP 2N RNG 65W MERIDIAN 6

Latitude: 40.092300 Longitude: -104.662712

Municipality (if within municipal boundaries): _____ County: WELD

Reference Location:

Facility Type: TANK BATTERY ☒ Facility/Location ID No 328384

☐ No Existing Facility or Location ID No.

☐ Well API No. (Only if the reference facility is well) 05- -

Fluid(s) Spilled/Released (please answer Yes/No):

Was one (1) barrel or more spilled outside of berms or secondary containment? No

Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.

Were Five (5) barrels or more spilled? No

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): 0

Estimated Condensate Spill Volume(bbl): Unknown

Estimated Flow Back Fluid Spill Volume(bbl): 0

Estimated Produced Water Spill Volume(bbl): Unknown

Estimated Other E&P Waste Spill Volume(bbl): 0

Estimated Drilling Fluid Spill Volume(bbl): 0

Specify: _____

Land Use:

Current Land Use: NON-CROP LAND

Other(Specify): _____

Weather Condition: 80's, Sunny

Surface Owner: FEE

Other(Specify): _____

Check if impacted or threatened by spill/Release (please answer Yes/No to all that apply):

Waters of the State ☐ Residence/Occupied Structure ☐ Livestock ☐ Public Byway ☐ Surface Water Supply Area ☐

As defined in COGCC 100-Series Rules

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

During maintenance activities, a leak was discovered along the dump line from the separator at the Mayer Et Al-62N65W/33NESE production facility. Approximately 210 cubic yards of impacted material have been excavated and transported to the Buffalo Ridge Landfill in Keenesburg, Colorado for disposal. Excavation activities are on-going at this location; groundwater has not been encountered. Excavation and confirmation sampling activities will be summarized in a subsequent Supplemental Form 19.

List Agencies and Other Parties Notified:

OTHER NOTIFICATIONS

Date	Agency/Party	Contact	Phone	Response
9/10/2015	County	Troy Swain	--Email	
9/16/2015	County	Roy Rudisill	--Email	
9/10/2015	Private	Land Owner	--Phone	

SPILL/RELEASE DETAIL REPORTS

#1	Supplemental Report Date: 09/18/2015		
FLUIDS	BBL's SPILLED	BBL's RECOVERED	Unknown
OIL	0	0	<input type="checkbox"/>
CONDENSATE			<input checked="" type="checkbox"/>
PRODUCED WATER			<input checked="" type="checkbox"/>
DRILLING FLUID	0	0	<input type="checkbox"/>
FLOW BACK FLUID	0	0	<input type="checkbox"/>
OTHER E&P WASTE	0	0	<input type="checkbox"/>
specify: _____			
Was spill/release completely contained within berms or secondary containment? <u>NO</u> Was an Emergency Pit constructed? <u>NO</u>			
<i>Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.</i>			
A Form 15 Pit Report shall be submitted within 30 calendar days after the construction of an emergency pit			
Impacted Media (Check all that apply) <input checked="" type="checkbox"/> Soil <input type="checkbox"/> Groundwater <input type="checkbox"/> Surface Water <input type="checkbox"/> Dry Drainage Feature			
Surface Area Impacted: Length of Impact (feet): 45		Width of Impact (feet): 40	
Depth of Impact (feet BGS): 19		Depth of Impact (inches BGS): _____	
How was extent determined?			
During maintenance activities, a leak was discovered along the dump line from the separator at the Mayer Et Al-62N65W/33NESE production facility. Approximately 1,210 cubic yards of impacted material have been excavated and transported to the Buffalo Ridge Landfill in Keenesburg, Colorado for disposal. Excavation activities are on-going at this location; groundwater has not been encountered. Excavation and confirmation sampling activities will be summarized in a subsequent report.			
Soil/Geology Description:			
Silty clay			
Depth to Groundwater (feet BGS) 251		Number Water Wells within 1/2 mile radius: 12	
If less than 1 mile, distance in feet to nearest		Water Well 974	None <input type="checkbox"/>
		Wetlands	None <input checked="" type="checkbox"/>
		Livestock	None <input checked="" type="checkbox"/>
		Surface Water 730	None <input type="checkbox"/>
		Springs	None <input checked="" type="checkbox"/>
		Occupied Building 2680	None <input type="checkbox"/>
Additional Spill Details Not Provided Above:			

CORRECTIVE ACTIONS

#1	Supplemental Report Date: 09/18/2015
Cause of Spill (Check all that apply)	
<input type="checkbox"/> Human Error	<input checked="" type="checkbox"/> Equipment Failure
<input type="checkbox"/> Other (specify) _____	<input type="checkbox"/> Historical-Unknown
Describe Incident & Root Cause (include specific equipment and point of failure)	
During maintenance activities, a leak was discovered along the dump line from the separator.	
Describe measures taken to prevent the problem(s) from reoccurring:	
The dump lines will be replaced.	
Volume of Soil Excavated (cubic yards): 1210	
Disposition of Excavated Soil (attach documentation)	
<input checked="" type="checkbox"/> Offsite Disposal	<input type="checkbox"/> Onsite Treatment
<input type="checkbox"/> Other (specify) _____	
Volume of Impacted Ground Water Removed (bbls):	0
Volume of Impacted Surface Water Removed (bbls):	0

REQUEST FOR CLOSURE

Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.

Basis for Closure:

☐ Corrective Actions Completed (documentation attached)

☐ Work proceeding under an approved Form 27

Form 27 Remediation Project No: _____

OPERATOR COMMENTS:

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: _____ Print Name: Sam LaRue

Title: Senior HSE Representative Date: 09/18/2015 Email: Sam.LaRue@anadarko.com

COA Type

Description

--	--

Attachment Check List

Att Doc Num

Name

400901434	TOPOGRAPHIC MAP
400901435	FORM 19 SUBMITTED

Total Attach: 2 Files

General Comments

User Group

Comment

Comment Date

--	--	--

Total: 0 comment(s)