

Document Number:
400903103

Date Received:
09/29/2015

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 96850 Contact Name: Tony Franzone

Name of Operator: WPX ENERGY ROCKY MOUNTAIN LLC Phone: (970) 589-1454

Address: PO BOX 370 Fax: _____

City: PARACHUTE State: CO Zip: 81635 Email: anthony.franzone@wpxenergy.com

For "Intent" 24 hour notice required, Name: Longworth, Mike Tel: (970) 812-7644

COGCC contact: Email: mike.longworth@state.co.us

API Number 05-045-14137-00 Well Number: GM 434-36

Well Name: WILLIAMS

Location: QtrQtr: SWSE Section: 36 Township: 6S Range: 96W Meridian: 6

County: GARFIELD Federal, Indian or State Lease Number: COC62743

Field Name: GRAND VALLEY Field Number: 31290

Notice of Intent to Abandon Subsequent Report of Abandonment

Only Complete the Following Background Information for Intent to Abandon

Latitude: 39.475683 Longitude: -108.057268

GPS Data:
Date of Measurement: 12/17/2007 PDOP Reading: 2.1 GPS Instrument Operator's Name: LAUREN VANCE

Reason for Abandonment: Dry Production for Sub-economic Mechanical Problems
 Other _____

Casing to be pulled: Yes No Estimated Depth: _____

Fish in Hole: Yes No If yes, explain details below

Wellbore has Uncemented Casing leaks: Yes No If yes, explain details below

Details: Suspected casing leak 4-1/2" in the 3720-4020' interval.

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
WILLIAMS FORK	5060	6673			

Total: 1 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
CONDUCTOR	24	18	48	45	25	45	0	VISU
SURF	13+1/2	9+5/8	32.3	1,103	315	1,103	0	VISU
1ST	7+7/8	4+1/2	11.6	6,872	845	6,872	3,500	CBL

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 5000 with 2 sacks cmt on top. CIBP #2: Depth 1200 with 8 sacks cmt on top.
 CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
 CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:

Perforate and squeeze at 1150 ft. with 35 sacks. Leave at least 100 ft. in casing _____ CICR Depth
 Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
 Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
(Cast Iron Cement Retainer Depth)

Set 27 sacks half in. half out surface casing from 1050 ft. to 1150 ft. Plug Tagged:
 Set 18 sacks at surface
 Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No
 Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing Plugging Date: _____
 *Wireline Contractor: _____ *Cementing Contractor: _____
 Type of Cement and Additives Used: _____
 Flowline/Pipeline has been abandoned per Rule 1103 Yes No *ATTACH JOB SUMMARY

Technical Detail/Comments:

Zone: All Perforations

Existing Perforations: Depth Holes

5060-5325	22
5566-5752	15
5890-6040	19
6146-6673	41
97 total	

Proposed Procedure :

- 1 Notify COGCC 48 hrs prior to start of activity via electronic Form 42
- 2 Set CIBP + 2 sks cement at 5000' ft in 4-1/2" casing
- 3 Pressure test 4-1/2" casing, pump cement into leaking area, if necessary
- 4 Set CIBP at 1200' in 4-1/2" casing, perforate 4-1/2" casing with 3 holes phased 120°, at 1150'
- 5 Place a cement plug to cover 4-1/2" backside from perforations to 50' into 9-5/8", and leaving 100' cement in 4-1/2", with a 30% open hole cement excess
- 6 Cut off 9-5/8" and 4-1/2" casing to 4-ft below ground level
- 7 Apply a 50-ft cement plug from surface in 4-1/2" - 9-5/8" annulus
- 8 Place a 50-ft surface cement plug inside 4-1/2" casing
- 9 Weld in place dryhole marker
- 10 Backfill cellar
- 11 Properly abandon flowlines per Rule 1103. File electronic Form 42 after flowline abandonment is complete

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Vicki Schoeber

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: BURGER, CRAIGDate: 9/30/2015**CONDITIONS OF APPROVAL, IF ANY:** _____Expiration Date: 3/29/2016**COA Type****Description**

	1) Provide 48 hour notice of plugging MIRU via electronic Form 42. 2) Contact COGCC Engineer with confirmed interval of casing leaks, rate established into casing leaks and planned cement volume. 3) Properly abandon flowlines per Rule 1103. File electronic Form 42 when flowline abandonment is complete.
--	---

Attachment Check List**Att Doc Num****Name**

400903121	PROPOSED PLUGGING PROCEDURE
400903122	WELLBORE DIAGRAM
400903123	WELLBORE DIAGRAM

Total Attach: 3 Files

General Comments**User Group****Comment****Comment Date**

Engineer	Added conductor to casing tab. Suspected leak interval is from about the MVRD top to 300' below.	9/30/2015 1:50:53 PM
Public Room	Document verification complete 9/29/15	9/29/2015 11:55:30 AM

Total: 2 comment(s)