

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

400917755

Date Received:

10/14/2015

Spill report taken by:

ALLISON, RICK

Spill/Release Point ID:

442543

SPILL/RELEASE REPORT (SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Any spill or release which may impact waters of the State must be reported as soon as practicable; any spill over 20 bbls must be reported within 24 hours and all spills over five bbls must be reported within ten days. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

OPERATOR INFORMATION

| | | |
|--|---------------------------|------------------------------------|
| Name of Operator: <u>WHITING OIL & GAS CORPORATION</u> | Operator No: <u>96155</u> | Phone Numbers |
| Address: <u>1700 BROADWAY STE 2300</u> | | Phone: <u>(970) 4932900</u> |
| City: <u>DENVER</u> | State: <u>CO</u> | Mobile: <u>(432) 6616647</u> |
| Zip: <u>80290</u> | | Email: <u>kyle.waggoner@whitin</u> |
| Contact Person: <u>Kyle Waggoner</u> | | <u>g.com</u> |

INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 400870238

Initial Report Date: 07/17/2015 Date of Discovery: 07/16/2015 Spill Type: Recent Spill

Spill/Release Point Location:

Location of Spill/Release: QTRQTR SWNE SEC 11 TWP 10n RNG 58w MERIDIAN 6

Latitude: 40.854164 Longitude: -103.832767

Municipality (if within municipal boundaries): _____ County: WELD

Reference Location:

Facility Type: TANK BATTERY ☒ Facility/Location ID No 436611

☐ No Existing Facility or Location ID No.

☐ Well API No. (Only if the reference facility is well) 05- -

Fluid(s) Spilled/Released (please answer Yes/No):

Was one (1) barrel or more spilled outside of berms or secondary containment? No

Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.

Were Five (5) barrels or more spilled? Yes

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): >=5 and <100

Estimated Condensate Spill Volume(bbl): 0

Estimated Flow Back Fluid Spill Volume(bbl): 0

Estimated Produced Water Spill Volume(bbl): 0

Estimated Other E&P Waste Spill Volume(bbl): 0

Estimated Drilling Fluid Spill Volume(bbl): 0

Specify: 14.5 bbls of oil released inside berm

Land Use:

Current Land Use: NON-CROP LAND

Other(Specify): Rangeland

Weather Condition: Sunny

Surface Owner: FEE

Other(Specify): Timbro Ranch and Cattle Co

Check if impacted or threatened by spill/Release (please answer Yes/No to all that apply):

Waters of the State ☐ Residence/Occupied Structure ☐ Livestock ☐ Public Byway ☐ Surface Water Supply Area ☐

As defined in COGCC 100-Series Rules

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

14.5 bbls of oil was released due to a stuck dump valve on a separator causing a tank to overflow. Liquid was contained inside secondary containment. Free liquid was recovered with a vacuum truck and impacted soils were excavated and placed on a plastic liner for onsite treatment.

List Agencies and Other Parties Notified:

OTHER NOTIFICATIONS

| Date | Agency/Party | Contact | Phone | Response |
|-----------|--------------|--------------------------|--------------|----------|
| 7/17/2015 | Landowner | Timbro Ranch & Cattle Co | 970-396-5885 | Notified |

CORRECTIVE ACTIONS

| | | |
|----|---------------------------|------------|
| #1 | Supplemental Report Date: | 10/14/2015 |
|----|---------------------------|------------|

Cause of Spill (Check all that apply) ☐ Human Error ☒ Equipment Failure ☐ Historical-Unknown
☐ Other (specify) _____

Describe Incident & Root Cause (include specific equipment and point of failure)

Equipment failure of dump valve.

Describe measures taken to prevent the problem(s) from reoccurring:

Dump valve has been repaired and tested.

Volume of Soil Excavated (cubic yards): 136

Disposition of Excavated Soil (attach documentation) ☒ Offsite Disposal ☐ Onsite Treatment
☐ Other (specify) _____

Volume of Impacted Ground Water Removed (bbls): 0

Volume of Impacted Surface Water Removed (bbls): 0

REQUEST FOR CLOSURE

Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.

Basis for Closure: ☐ Corrective Actions Completed (documentation attached)
☐ Work proceeding under an approved Form 27
Form 27 Remediation Project No: _____

OPERATOR COMMENTS:

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: _____ Print Name: Kyle Waggoner

Title: Field Regulatory Manager Date: 10/14/2015 Email: kyle.waggoner@whiting.com

Attachment Check List

| <u>Att Doc Num</u> | <u>Name</u> |
|--------------------|--------------------|
| 400917774 | ANALYTICAL RESULTS |
| 400917775 | OTHER |
| 400917776 | SITE MAP |
| 400917777 | SITE MAP |
| 400917778 | TOPOGRAPHIC MAP |
| 400917845 | DISPOSAL MANIFEST |

Total Attach: 6 Files

General Comments

| <u>User Group</u> | <u>Comment</u> | <u>Comment Date</u> |
|-------------------|----------------|---------------------|
| | | |

Total: 0 comment(s)