

Surprise Central Facility

Inspection# 673402535

2 tanks without NFPA
diamond. (Rest of tanks
contain diamond) Trash in
foreground outside of berm.



Tank battery with low spots
at loadouts visible.



1 enclosed flare, 1
unenclosed flare, both
lit.



Topsoil pile on south
side of location with no
visible protection or
preservation.



Topsoil pile on west side of
location with no visible
protection or preservation.

