

Document Number:
400922986

Date Received:
11/02/2015

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 8960 Contact Name: Bryan Brown

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY Phone: (720) 440-6100

Address: 410 17TH STREET SUITE #1400 Fax: (720) 279-2331

City: DENVER State: CO Zip: 80202 Email: bbrown@bonanzacrck.com

For "Intent" 24 hour notice required, Name: Rains, Bill Tel: (970) 590-6480

COGCC contact: Email: bill.rains@state.co.us

API Number 05-123-05157-00

Well Name: STATE-32 Well Number: 1

Location: QtrQtr: SENW Section: 32 Township: 5N Range: 61W Meridian: 6

County: WELD Federal, Indian or State Lease Number: _____

Field Name: WILDCAT Field Number: 99999

Notice of Intent to Abandon Subsequent Report of Abandonment

Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.359007 Longitude: -104.235164

GPS Data:
Date of Measurement: 03/21/2014 PDOP Reading: 1.9 GPS Instrument Operator's Name: Wyatt Hall

Reason for Abandonment: Dry Production for Sub-economic Mechanical Problems

Other Re-enter for offset frac

Casing to be pulled: Yes No Estimated Depth: _____

Fish in Hole: Yes No If yes, explain details below

Wellbore has Uncemented Casing leaks: Yes No If yes, explain details below

Details: _____

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth

Total: 0 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
SURF	12+1/4	10+3/4	32.75	150		150	0	CALC
OPEN HOLE	7+7/8			6,779				

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth _____ with _____ sacks cmt on top. CIBP #2: Depth _____ with _____ sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 300 sks cmt from 3400 ft. to 2890 ft. Plug Type: OPEN HOLE Plug Tagged:
Set 300 sks cmt from 700 ft. to 0 ft. Plug Type: OPEN HOLE Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
(Cast Iron Cement Retainer Depth)

Set _____ sacks half in. half out surface casing from _____ ft. to _____ ft. Plug Tagged:

Set _____ sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing Plugging Date: _____

*Wireline Contractor: _____ *Cementing Contractor: _____

Type of Cement and Additives Used: _____

Flowline/Pipeline has been abandoned per Rule 1103 Yes No *ATTACH JOB SUMMARY

Technical Detail/Comments:

Surface hole size unknown.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Bryan Brown

Title: Production Engineer Date: 11/2/2015 Email: bbrown@bonanzacrk.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: JENKINS, STEVE Date: 11/6/2015

CONDITIONS OF APPROVAL, IF ANY: _____

Expiration Date: 5/5/2016

COA Type

Description

1) For 700' plug: pump plug and displace. If surface casing plug is not circulated to surface then tag plug – must be 50' or shallower and provide 10 sx plug at the surface. Leave at least 100' of cement in the casing for each plug.

Attachment Check List

<u>Att Doc Num</u>	<u>Name</u>
400922986	FORM 6 INTENT SUBMITTED
400923037	LOCATION PHOTO
400923059	PROPOSED PLUGGING PROCEDURE
400923061	WELLBORE DIAGRAM
400923062	WELLBORE DIAGRAM
400928819	SURFACE OWNER CONSENT

Total Attach: 6 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Public Room	Document verification complete 11/4/15	11/4/2015 3:01:20 PM

Total: 1 comment(s)