

Click here to reset form



State of Colorado
Oil and Gas Conservation Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203 (303) 894-2100 Fax: (303) 894-2109

FOR OGCC USE ONLY

ACCIDENT REPORT

As required by Rule 602.b.

Report taken by:

DESCRIPTION OF ACCIDENT (Please be as specific as possible)

Name of Operator: <u>Overland Resources LLC per COGIS</u>	Location
Date of Incident: <u>November 25, 2015</u>	County: <u>Arapahoe</u>
Type of Facility (well, tank battery, flow line, pit): <u>Tank Battery</u>	Field Name: <u>Dragoon</u>
Well Name and Number: <u>REEVES 28-31</u>	QtrQtr: <u>NWNE</u> Section: <u>28</u>
API Number: <u>05-005-06345</u>	Township: <u>4S</u> Range: <u>62W</u>
Connect to Accident (land owner, royalty owner, etc.): <u>Pumper</u>	Meridian: <u>6</u>

Provide a detailed description of the accident, problem, and cause (equipment failure, human error, etc.):

According to the Vic Behrens of Behren Resources Inc. which pumps the Reeves 28-31 lease, shortly before 6:10am the morning of November 25, 2015 the Reeves treater caught fire. Vic reports that it "looks like the fire tube gasket leaked."

Vic worked with the local authorities including the Arapahoe County Sherrifs Office to resolve the issue. Based on the evidence, the cause of the fire was equipment failure.

OTHER NOTIFICATIONS

List the parties and agencies notified (County, BLM, EPA, DOT, Local Emergency Planning Coordinator or other).

Date	Agency	Contact Person	Response

Accident Tracking No: _____