




Rem: 4325  
 API: 075-07533  
 Doc #: 200221063  
 Date: 10/27/2009

# COGIS - Field Inspection Report

|  |  |
|--|--|
|    |  |
| API Number: <b>05-075-07533</b>  | Name: <b>KNUDSEN #7</b>                        |
| Location: <b>NWNE 6 8N 52W</b>   | Lat: <b>40.69545</b> Long: <b>-103.230989</b>  |
| Operator #: <b>46290</b>   | Operator Name: <b>K P KAUFFMAN COMPANY INC</b> |
| Inspection Date: <b>10/27/2009</b>   | Inspector: <b>John Axelson</b>                 |

Inspection was: **Unsatisfactory**

Insp. Type: **ES**      Insp. Stat: **PR**      Reclamation (Pass, Interim or Fail):      P&A (Pass/Fail):  
 Brhd. Pressure:      Inj. Pressure:      T-C Ann. Pressure:      UIC Violation Type:  
 Violation: **Y**      NOAV Sent: **Y**      Date Corrective Action Due: **11/30/2009**      Date Remedied:

## Pit Inspection

Pit Type: **PW**      Oil on Pit: **N**      Freeboard:  
 Number of Pits: **2**      Number covered or lined: **0**      Number uncovered or unlined: **0**

Comments: **50' X 50' AND APPROX 50' X 90' USED IN CASE OF OVERFLOW FROM FIBERGLASS WATER TANK.**

## Field Inspection Comments and Observations

| Insp. Comment | Inspection/Violation Comments  |
|---------------|--|
| ACTION        | IMMEDIATELY CLEANUP OILY SOIL AT WELL HEAD IN ACCORDANCE WITH COGCC RULE 907.E. REMOVE AND PROPERLY DISPOSE OR RECYCLE TRASH AND JUNK AT WELLHEAD. PROPERLY DISPOSE OF CONTAMINATED SOIL STOCKPILE IN ACCORDANCE WITH 907.E. AND PROVIDE COGCC WITH APPROPRIATE WASTE DISPOSAL DOCUMENTATION IN ACCORDANCE WITH 907.B.(2). CONTROL WEEDS AT WATER PITS.  |
| FIREWALL      | GOOD   |
| GENHOUSE      | SOME JUNK/TRASH AT WELL HEAD. NEED WEED CONTROL AT WATER PITS.   |
| MISC          | TANKS WERE RECENTLY PAINTED. THREE STEEL PRODUCTION TANKS ARE PROPERLY LABELED. NEED CAPACITY ON FIBERGLASS WATER TANK. TANKS AT INJECTION NEED TO BE LABELED.   |
| SPILCOM       | OILY SOIL AT WELLHEAD OBSERVED DURING 4/27/09 INSPECTION HAS NOT BEEN CLEANED UP. STOCKPILE OF OILY SOIL FROM SKIM PIT CLOSURE IS STILL ON LOCATION AND DOES NOT COMPLY WITH 907E.(2) REQUIREMENTS FOR LAND TREATMENT. IT DOES NOT APPEAR STOCKPILE HAS BEEN ALTERED SINCE INSPECTION ON 4/27/09. STORMWATER HAS POOLED IN LOW AREA ON TOP OF STOCKPILE. |
| TANKBAT       | 3: 200 BBL STEEL PRODUCTION TANKS, VERTICAL TREATER, 200 BBL FIBERGLASS WATER TANK   |