



# United States Department of the Interior



BUREAU OF LAND MANAGEMENT  
Colorado State Office  
2850 Youngfield Street  
Lakewood, Colorado 80215-7210  
www.co.blm.gov

In Reply Refer To:  
3180 (CO-922)  
Cathedral Bluffs Unit  
COC76070X

**DEC 17 2015**

Encana Oil & Gas (USA) Inc.  
Attn: Judy Tatham  
370 17<sup>th</sup> Street, Suite 1700  
Denver, CO 80202

Dear Ms. Tatham:

The Bureau of Land Management (BLM) has determined that the following well is NOT capable of producing unitized substances in paying quantities under the existing conditions:

Well Name	API Number	Surface Location	Report
<b>CBU DHN8B-1 A11 2100</b>	05-103-11886	NENE, Sec. 11, T2S R100W 6 <sup>th</sup> P.M.	Lease COC63934 & COC56840

The production will be handled on a lease basis for the CBU DHN8B-1 A11 2100 well. Since the CBU DHN8B-1 A11 2100 well was determined to be a nonpaying unit well and the lateral intersects two Federal leases, a drilling and spacing unit must be established for the well, so the BLM White River Field Office can approve a communitization agreement. Please notify the BLM White River Field Office (Reneta Kawcak at (970) 878-3867) when the drilling and spacing unit is approved.

Please contact Peter Cowan, Petroleum Engineer, at (303) 239-3939 if you have any questions regarding this matter.

Sincerely,

Suzanne Mehlhoff  
Chief, Branch of Fluid Minerals  
Division of Energy, Lands, and Minerals